RTR Services Inc.					Re L				RTR #: 407 ACCOUNT NUMBER:				072813			
FORKLIFT									ACCOUNT NUMBER:							
CONDITION REPORT				0-0				ACCOUNT NAME:								
YEAR: 2020			VIN/SN: FGB1C-3460-00079							CAPACITY: 11,850						
MAKE: Doosan					X W	AREHOL	ISE MOD									
MODEL: GC55C-9					COLOR: EXTERIOR: Orange/ Black INTERIOR: Bla						Black					
ENGINE:					KEYS	: IGNIT	ION: 🛛 YES 🗌 NO 🗌 N/A 🔸 DOOR: 🗌 YES 🖾 NO 🗌 N/A						Α			
TRANS:				FUEL: DIESEL GAS PROPANE ELECTRIC												
HRS: 1,933				DOES	IT RUN					CAN IT BE I	DRIVEN?	\bowtie	YES		JNK	
				50					L APPEARA	INCE					ADTIONO	
	FRONT		GD	FR		N/A	COMM	IENIS						PWR		
	HEAD LIG	GHTS		\boxtimes											BRAKES	
	HOOD TURN SIGNALS GRILL L FRONT FENDER L DOOR L REAR PANEL					\boxtimes									LOSED CAB	
						\boxtimes									ED GLASS	
					┼┼									HEA		
						\boxtimes							ㅓ님			
¥				\boxtimes			Scratc	hes or	n surface					AM F	M RADIO	
ворү	-	SAFETY LIGHTS		\square			_	-							E DECK	
Ш		REAR TAIL LIGHTS					Scratc	hes or	n surface					-	PLAYER FLAPS	
	FRAME TURN SIGNALS			\boxtimes										2WD		
														4WD		
	R FRONT FENDER R FRONT DOOR R REAR PANEL WORK LIGHTS TOP			\square									\square		HION TIRES	
						\boxtimes									UMATIC TIRES	
				\boxtimes											T HEIGHT 86" MAST HT 120	
				\boxtimes	ΙH										ANGLE	
	L FRONT			\boxtimes			50 %	305-40	6.4 SIZE:					FOR	K LENGTH	
RES	L REAR	R FRONT		\boxtimes					8 SIZE:					-	K WIDTH	
TIR				\boxtimes			50 % 305-406.4 SIZE: 50 % 203.308 SIZE:									
		WINDSHIELD					50 %	203.30	8 SIZE:					-	E SHIFT K POSITIONER	s
SS	L DOOR					\boxtimes							ㅓ님	-	K ROTATOR	U
GLA\$	REAR WINDOW R DOOR					\boxtimes									H-PULL UNIT	
ß														-	K EXTENSIONS	5
MIRROR DASH/G														ROP	:H	
ERIOR	DOOR PA					\boxtimes							ㅓ님	-	RGER	
ERI	SEAT			\boxtimes			Left side tear in seat (5x5)						NT STABILIERS	S		
				\boxtimes												
	- CONTROLS		GD	FR	PR		N/A	CO1	MENTS:							
ENGIN								00					ㅓ님			
		TRANSMISSION														
MECHANICAL	CLUTCH						\square									
Ň				\boxtimes												
H	2 ND DIFFERENTIAL BRAKES			\boxtimes												
ΛEC	FRONT END			\boxtimes												
~	REAR END			\boxtimes												
		Y/ELECTR						1.1						-1		
	COMMENTS: Hours unverified. Right rear tire has 3 inch chunk/split in the rubber. Left front tire has 2 inch chunk missing from rubber.															
							11/2	20/24								
	EM	PLOYEE'S FULL	NAME (P	LEASE	PRINT)			DATE			EMI	PLOYEE'S S	IGNATL	IRE	<u> </u>	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107