RTR Services Inc. BOX TRUCK									RTR #: 4073479 ACCOUNT NUMBER:					75	5			
CONDITION REPORT									ACCOUNT NAME:									
YEAR: 2016			MIL		ES	358,727			VIN#:	5PVNJ8JVXG4S61666								
MAKE: Hind		Hino		GVW:		25,950 BC		X HEIGHT	13'	BOX LEN	LENGTH 26'			BOX WIDTH				
MODEL:		268		WH	WHEELBASE:				COLOR: I	EXTERIOR: White			INTERIOR:			ack		
ENGINE:		J08DTF/TW		HP					YS: IGNITION: ⊠ YES ☐ NO • DOOR:		OOR: [⊠ YES □ NO						
TRANS: Automatic			1			GAS 🖂			ANTIFREEZE TESTED: YES NO				RATIN					
DOES MOTOR RUN? YES NO CAN IT BE DRIVEN? YES NO COLLISION DAMAGE? YES NO PHYSICAL APPEARANCE														☑ NO				
			GD	FR	PR	N/A		MENTS	L APPEARA	INCE						OPTIOI	NS	
ВОДУ	FRONT BUMPER						CONT	ILN13										
	HEAD LIGHTS HOOD TURN SIGNALS													BR	BRAKES ☐ AIR			
				\boxtimes	\parallel							-						
	GRILL			\boxtimes										$\exists \ \Box$	PWR L	OCKS		
	D FRO	NT FENDER	$ \; \mid \; \mid \; \mid$				Micci	ng door la	tch. Hole in	door				$\dashv \exists$	PWR W		NS	
	D BOX		\boxtimes			WIISSII	ig door id	ton. Hole in	<u>uooi</u>				= = =	PWR N		RS		
	1	BUMPER		\boxtimes											AIR CC			
	REAR		\boxtimes	$ $									$\exists \exists$	AIR RII		SPENSION		
	P FRO	NT FENDER		\boxtimes											AM FM			
	P FRONT DOOR P BOX			\boxtimes											TAPE /			
	TOP			\boxtimes			Hole i	n roof on	D/S					<u> </u>			NT ROOF	
TIRES	D FRO			\boxtimes			40 %		ZE:						E-TRA			
	D REAR A1 (S/D?) D REAR A2 (S/D?)			\boxtimes			50 % 50 %		ZE: ZE:					$\exists \exists$	BOX D		IGHI	
	P FRONT						40 %	SIZ	ZE:						EL TANK			
	P REAR A1 (S/D?) P REAR A2 (S/D?)			\boxtimes			50 % 50 %		ZE: ZE:					-		GLE G	AL	
	SPARE						30 70	%	SIZE:						MUD F			
GLASS	WINDSHIELD D FRONT DOOR REAR WINDOW P FRONT DOOR						Cracked					WH	WHEELS					
							Tape holding P/S mirror				-	☐ ALC		VI				
											☐ BUD							
	MIRRORS DASH						Таре	holding P	S mirror					\dashv_{\bowtie}	☐ SPC		72	
INTERIOR	DOOR PANELS			\boxtimes											SPENSIO		· ——	
		SEAT(S)					Tear i	n P/S seat	t				☐ AIR					
	FLOORING HEADLINER SLEEPER			\boxtimes										-	⊠ SPF			
													$\exists \Box$	TANDEM AXLE				
	вох		GD	FR	PR	UKN	N/A	ape on wa				$\exists \exists$	ENGINE BRAKE TOOL BOX					
MECHANICAL	ENGIN			\boxtimes											LIFT/T		LE	
	1	TRANSMISSION													RAMP LIFT G	ATE		
	1	CLUTCH DIFFERENTIALS												$\exists \exists$	LIII	A1L		
	BRAKES			\boxtimes														
	FRONT END REAR END			\boxtimes										+ =				
	BATTE						Dead, u	ad, unable to jump			╛╘							
CO		GERATION S: Mileage un	verified				\boxtimes											
		. miloage all	. J															
<u> </u>																		
							8/	12/2024										
		EMPLOYEE'S FUL						DATE	n this range to be	true and assume	ito to the			SIGNATU				
		by Si	yrrature abi	ove iu0	петеру	ociuly all into	ormation C	ontanteu WitNi	n this report to be	, u u e anu accura	10 1116	nesi () i M	y Kriowie	uye aι βΓ	COCIII.			