RTR Services Inc. EXCAVATOR WHEEL/TRACK CONDITION REPORT									RTR #: 407350 ACCOUNT NUMBER: ACCOUNT NAME:										
YEAR: 2023				VIN/SN: SY0039CC50978				8											
MAKE: SANY MODEL: SY35U									Yellow				INITI	ERIOR:	Grav				
ENGINE: Yanmar 3TN			1//88							N/A •	DOC	OR: 🕅							
TRANS: Hyd										$\begin{array}{c c} NO \square N/A \bullet DOOR: \square YES \square NO \square N \\ \hline ANTIFREEZE TESTED: \square YES \square NO \\ \hline \end{array}$						RATING:			
HRS: 267					DOES IT RU						NK	CA	N IT BE			YES		NO	
PHYSICAL APPEARANCE																			
			GD FR		PR	N/A	COMN	IENTS							OPTIONS				
BODY	FRONT PANEL HEAD LIGHTS HOOD TURN SIGNALS GRILL L FRONT PANEL L DOOR															TINT AIR HEA AIR AM I TAP	ED G CONI TER RIDE FM R/ E DE	СК	
	L REAR PANEL SAFETY LIGHTS REAR PANEL TAIL LIGHTS FRAME TURN SIGNALS															BUC QUIC HYD	THU CK W		
	R FRONT PANEL R FRONT DOOR R REAR PANEL WORK LIGHTS TOP																		
TIRES	L FRONT L REAR (S/D?) R FRONT R REAR (S/D?) TRACKS						75%	% % %	SIZ SIZ SIZ SIZ	E: E:									
GLASS	WINDSHIELD						Broke	n out											
INTERIOR	DASH/GUAGES DOOR PANELS SEAT CARPET/MAT CONTROLS																		
-	ENGINE		GD	FR	PR		N/A	COW	MENTS										
MECHANICAL	DIFFERE UNDERC BRAKES FRONT I REAR E	TRANSMISSION DIFFERENTIAL UNDERCARRIAGE BRAKES FRONT END REAR END BATTERY/ELECTR																	
COMMENTS: Hours unverified. 8/2/2024																			

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107