RTR Services Inc. BOX TRUCK CONDITION REPORT		RTR #:	4073625
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2016	MILES	322,283	VIN#:	1HTMMMML0GH449145				
MAKE:	International	GVW:	25,999	BOX HEIGHT	97"	BOX LENGTH	26'	BOX WIDTH	97"
MODEL:	4300	WHEELBASE:		COLOR: EXTERIOR:	White	INTERIOR:	Gray		
ENGINE:	Cummins ISB 6.7L	HP		KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Automatic	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:			

DOES MOTOR RUN?	☐ YES	☒ NO	CAN IT BE DRIVEN?	☐ YES	☒ NO	COLLISION DAMAGE?	☐ YES	☒ NO

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILL	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D BOX	☐	☒	☐	☐	
	REAR BUMPER	☐	☒	☐	☐	
	TAIL LIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P BOX	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	40 % SIZE:
	D REAR A1 (S/D?)	☐	☒	☐	☐	80/80 % SIZE:
	D REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	P FRONT	☐	☒	☐	☐	40 % SIZE:
	P REAR A1 (S/D?)	☐	☒	☐	☐	80/80 % SIZE:
	P REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☐	☐	☒	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☐	☒	☐	
	FLOORING	☐	☒	☐	☐	
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☒	☐	☐	
	BOX	☐	☒	☐	☐	Custom sleeper installed

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☐	☒	☐	
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIALS	☐	☐	☐	☒	☐	
	BRAKES	☐	☐	☐	☒	☐	
	FRONT END	☐	☐	☐	☒	☐	
	REAR END	☐	☐	☐	☒	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	Replaced 8/2024
	REFRIGERATION	☐	☐	☐	☐	☒	

OPTIONS
☒ PWR STEERING
BRAKES
☒ AIR
☐ HYD
☒ PWR LOCKS
☒ PWR WINDOWS
☐ PWR SEATS
☐ PWR MIRRORS
☒ AIR CONDITIONER
☐ AIR RIDE SEAT D/P _____
☒ AIR RIDE SUSPENSION
☒ AM FM RADIO
☒ TAPE / CD / CB? _____
☒ SLEEPER SIZE? _____
☐ TRANSLUCENT ROOF
☒ E-TRACK LINING
☒ BOX DOME LIGHT
☐ SIDE DOOR
FUEL TANKS
☒ SINGLE GAL _____
☐ DUAL GAL _____
☒ MUD FLAPS
WHEELS
☐ ALUMINUM
☒ STEEL
☐ BUD
☐ SPOKE
☒ EXHAUST S/D? _____
SUSPENSION
☐ AIR
☒ SPRING
☐ PAD
☐ TANDEM AXLE
☐ ENGINE BRAKE
☐ TOOL BOX _____
☐ LIFT/TAG AXLE
☐ RAMP
☒ LIFT GATE
☐
☐
☐
☐
☐
☐

COMMENTS: Mileage unverified. Unit only cranks, will not turn over. Suspected to have a faulty injector pump and missing freeze plug.

8/7/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107