RTR Services Inc.						П					RTR #: 407379							94						
HEAVY TRUCK							1				ACCOUNT NUMBER:													
CONDITION REPORT					ی	<u> </u>					ACCOUNT NAME:													
YEAR:		2018	MII	LES	495,3	495,396				VIN#: 3AKNGND12JDJJ3063					3									
MAKE:		Freightliner	G۷	W:	73,720 LICE			ISE:					ST:		-	ΓAGS:	МО	NTH	1		YR:			
MODEL:		Coronado 122	WH	HEELI	BASE:		COLOR: EXTERIOR:				ВІ	ack		INTERIOR:										
ENGINE:		Detroit DD16	HP			во	DDY TYPE: Sle			eeper			KEYS: IGNITION: ⊠ YE			⊠ YES	NO • DOOR:				⊠ YES	S 🗌 NO		
TRANS:		Eaton 18sp. l	FU	EL: [GAS	⊠ I	DIESEL AN			ITIFREEZE TE			ESTED: ☐ YES ⊠ NO			RATING:								
	DOES M	OTOR RUN?	⊠ YE	s [□ NC)	CA	AN IT BE DRIVEN			?	⊠ YES		□ NO	C	DLLIS	ION DA	MAGI	E?	□ Y	ES	⊠ N	10	
PHYSICAL APPEARANCE																								
BODY			GD	FR	PR	N/A	\	COM	/IENTS	3									_			ONS		
	FRONT HEAD I	BUMPER		\boxtimes			F											_ [2	_	PWR : KES	STEI	ERING		
	HOOD	LIGHTS		\boxtimes			-									┩╹		ARES						
	TURN SIGNALS GRILL			\boxtimes			-											HYD						
				\boxtimes															_	PWR I				
	D FROI D DOO	NT FENDER	╽႘╽		ᅵ片		F											_ ₽	_			DOWS		
	D SLEE		\boxtimes	$\ \cdot\ $		F											-	=	PWR :					
	REAR		\boxtimes	╽	╅													_			ITION	ER		
	TAIL LI		\boxtimes																		SEAT			
	REAR																	_ ₽	_			SUSPE WHEE	ENSION	
	P FRONT FENDER P FRONT DOOR			$\boxtimes \boxtimes$	$\ \cdot\ $		F											$-\mid \Box$	_			WHE		
	P SLEE					F												_	AM FI					
	TOP		\boxtimes																		/ CB?			
TIRES	D FRONT						L	75 %										_ [_	_		SIZE?		
	D REAR A1 (S/D?) D REAR A2 (S/D?)			$\boxtimes \boxtimes$			F	80 % 80 %											=	GLAD		AL PI	GIAIL	
		P FRONT					F	75 %										_	_	L TAN		100		
	P REAR A1 (S/D?) P REAR A2 (S/D?) SPARE			\boxtimes				80 %														GAL		
				\boxtimes			L	80 % 27580R22.5 SIZE: 80 % 27580R22.5 SIZE:					\dashv $_{\scriptscriptstyle{F}}$	_			3AL <u>16</u>	<u> </u>						
GLASS	WINDSHIELD D FRONT DOOR REAR WINDOW			\boxtimes	H	+ =		80 %	2/580	JK22	.5 8	oize:						₽ 	_	MUD I	-LAI	-5		
				\boxtimes			Ĺ													⊠ AL	UMI	NUM		
																				☐ ST				
9		P FRONT DOOR MIRRORS		\boxtimes			L													⊠ BU				
	DASH	KO			H	$+ \exists$												\dashv ${}_{\triangleright}$		_	-	S/D?	D	
R	DOOR PANELS			\boxtimes			-												_	PENSI			_	
RIO		SEAT(S)		\boxtimes																⊠ AIF				
単 CARP ≧ HEAD							L															3		
=	HEADLINER SLEEPER		$\mid \; \mid \; \mid \; \mid$	\boxtimes	╏╏	$\parallel \parallel$	F												_	□ PA TAND		ΔXIF		
	<u> </u>		GD	FR	PR	UKN	1	N/A	CON	ИΜЕ	NTS	S:							_			RAKE		
MECHANICAL	ENGIN																			TOOL				
		TRANSMISSION																-	_	LIFT/1 WET I		AXLE		
	CLUTCH DIFFERENTIALS			\boxtimes														╗		VV	M I			
		BRAKES		\boxtimes																				
	_	FRONT END]					
	REARI			\boxtimes	ᅵ뮈	\parallel		\Box	Pan	laco	۲ ۵/ ₋	2024						4						
BATTERY/ELECTR \(\triangle \) \(\triangle \) \(\triangle \) Replaced 8/2024 \(\triangle \) COMMENTS: Milage Unverified. Unit does not build up or retain air pressure for unknown reason. Can be driven but will lose pressure.																								
7/17/2024																								
		EMPLOYEE'S FULI	NAME (PI FASE	PRINT					Z4 TE			_			FME	LOYEE'S	SIGNA	TUR	F			_	
							infor	mation co			n this i	report to be	true	and accura	ate to th								_	