	BC	Services In OX TRUCK								RTR #: 4073865 ACCOUNT NUMBER:							
									ACCOUNT NAME: VIN#: 1HTMMMML6KH570268								
YEAR: MAKE:		2019 International			MILES 249,578 GVW: 25,999			BOX HEIGHT		BOX LEN		26'	BOX	WIDTH	100"		
		4300			WHEELBASE:		BOX HEIC		-	EXTERIOR:	Wh		INTER			av	
ENGINE:		Cummins ISB 6.7I		HP	HP				EYS: IGNITION: X YES NO • DOOR:				,				
TRANS: Automatic			FUEL: G		GAS 🗵			NTIFREEZE TESTED: 🗌 YES 🖾 NO			RATING:						
DOES MOTOR RUN? 🛛 YES		s [5 🗌 NO 🛛 C/		AN IT BE DRIVEN		? 🛛 YES 🗌 NO COLLISION DA		MAGE?								
PHYSICAL APPEARANCE																	
BODY	FRONT	GD	FR	PR	N/A	COM	MENTS						PWR S		-		
		LIGHTS		\boxtimes										BRAKES			
	HOOD TURN SIGNALS GRILL			\boxtimes										⊠ AIR □ HYD			
				\boxtimes										PWR L		i	
	D FRONT FENDER D DOOR			\boxtimes										PWR W PWR S		WS	
	DBOX			\boxtimes										PWR N	-	RS	
				\boxtimes									\square			ONER AT D/P D	
	REAR PANEL			\boxtimes												SPENSION	
	P FRONT FENDER P FRONT DOOR			\boxtimes										AM FM TAPE /			
	-	P BOX		\boxtimes										SLEEP			
	TOP D FRONT			\boxtimes			00.9/	110225	817E					-			
TIRES	D REAR A1 (S/D?)							11R22.5 % 11R22					■ E-TRACK LINING ■ BOX DOME LIGHT				
	D REAR A2 (S/D?)					\boxtimes	00.0/	%	SIZE:					SIDE D			
	P REAR A1 (S/D?)			\boxtimes				11R22.5 % 11R22						EL TANK	-	AL <u>70</u>	
	P REAR A2 (S/D?) SPARE							%	SIZE:							L	
		WINDSHIELD						%	SIZE:				⊠ ₩H	MUD F	LAPS		
SS	D FRONT DOOR			\boxtimes												М	
GLA		REAR WINDOW P FRONT DOOR MIRRORS		\boxtimes													
				\boxtimes												D 0 O	
~	DASH DOOR PANELS SEAT(S)			\boxtimes										EXHAL SPENSIC		D? <u>S</u>	
RIOR				\boxtimes										🖾 AIR			
INTEF	FLOORING HEADLINER			\boxtimes													
≤	SLEEPER			\boxtimes										TANDE	M AX		
	BOX		GD	FR	PR		N/A	COMM	ENTS:					ENGIN TOOL		KE	
MECHANICAL		ENGINE		\boxtimes										LIFT/T/		ίLΕ	
	CLUTC	MISSION		\square			\square							RAMP LIFT G	ATE		
	DIFFERENTIALS			\boxtimes													
	BRAKES FRONT END REAR END BATTERY/ELECTR REFRIGERATION			\boxtimes													
				\boxtimes													
COMMENTS: Mileage unverified. Maxon lift gate, S/N: 1802425281. Box model: PAV260102102, S/N: SO-31211. Box dome light is loose.																	
							7/	30/2024									

7/30/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107