RTR Services Inc.												RTR #: 4073883											
HEAVY TRUCK												ACCOUNT NUMBER:											
CONDITION REP			RT		ا			<u> </u>		ACCOUNT NAME:													
YEAR:		2016		МІ	LES	754,4	48	18			VIN#: 3HSDJAPR8GN0			R8GN0	00247								
MAKE:		International	G۱	GVW:			LICENSE:					ST: TAGS:		MON	ТН		YR:						
MODEL:		Prostar +	WI	WHEELBASE:						OLOR:	EX	TERIOR: Blue				INTE	RIO	R:	Gray				
ENGINE:		Cummins ISX 14.9L			45	0	BODY TYPE: S			Sleep	er		KEYS: IGNITION: ⊠ YES [□ №	NO • DOOR: ⊠ YES						
TRANS:		Automatic	FU	IEL: [GAS	AS DIESEL AN				NTIFREEZE TESTED: YES NO					RATI	NG							
DOES M		OTOR RUN?	RUN? ⊠ YE		S □ NO		CAN	CAN IT BE DRI		N?	N? ⊠ YES		□ NO COLL		LLISI	LISION DAM		?	⊠ YES		10		
							PHYSICAL APPEAR				NC	E											
			GD	FR	PR	N/A	. 0	СОММ	ENTS										ОРТ	IONS			
ВОВУ	_	BUMPER][WR STE	ERING				
	HEAD I	LIGHTS					-									BR	AK	.ES ☑ AIR					
	TURN SIGNALS			\boxtimes														HYD					
	GRILL			\boxtimes													WR LO						
	D FROI D DOO						Damaged									✓ PWR WINDOWS✓ PWR SEATS							
	D SLEE			H												$\dashv \square$		WR MIR					
	REAR																	IR CON		ER			
	TAIL LIGHTS [<u> </u>												IR RIDE				
	P FROI						Damaged Missing piece											IR RIDE					
	_	NT DOOR		\boxtimes					g p.ooc								╛┇		LIDING				
	P SLEE															M FM R							
	TOP																	TAPE / CD / CB? CD/CB					
	D FROI		\boxtimes					295/75R										LEEPER	R SIZE?	TWIN_			
TIRES	D REAL							295/75R										LECTRI	_	GTAIL			
	D REAL					65 % 295/75R22.5 SIZE: 0 % 295/75R22.5 SIZE:										_	LAD HA TANKS	ANDS					
	PREA				1 5										٦.٥		SINGL	E GAL					
	P REAR A2 (S/D?)			\boxtimes			4	45 % 275/80R22.5 SIZE:						DUAL GAL									
	SPARE					-	% SIZE:									│ │ │ MUD FLAPS │ WHEELS							
SS	D FRONT DOOR					1 5		JI acke	·u								⊣ '''		.LO ☑ ALUM	INUM			
S D FRO		WINDOW													_	STEE	L						
														=] BUD] SPOK	_							
	DASH	NO.			╁	╅											\dashv	_	XHAUS				
S.		PANELS		\boxtimes													SU	_	ENSION				
SEAT(_	AIR				
Ē	CARPET HEADLINER						-] SPRIN] PAD	IG			
	SLEEP															ANDEM	AXLE						
MECHANICAL	ENGIN	=	GD	FR	PR	UKI		N/A	Chack			۸۲	S Lights	Or 0	il Dan	l col-			NGINE I				
		ENGINE TRANSMISSION CLUTCH DIFFERENTIALS BRAKES FRONT END				$\parallel \parallel$		<u> </u>	Trans			AB	S Lights	On. O	II Pan	Leak	┦믐		OOL BO				
	CLUTC					\boxtimes		5 [Lean							VET KIT					
								맄															
								┪ ┡															
	REAR END						=										╛╘						
-		RY/ELECTR					<u> </u>		New b						- l - '			 .					
COMMENTS: Mileage unverfied. Unit was found to have blown airbags on the forward drive axle and a leaking front drive axle air springs and crank seal. It is not recommended that this truck be driven due to the oil leak and the torn airbags. Battery door broken. Left tail light hanging.												ıs and nging.											
Active Faults: SPN 2023 – FMI 3, SPN 1552 – FMI 2, SPN 791 – FMI 2 – Flash Code 4-3, SPN 1059 – FMI – 2 – Flash Code 24-3, OEM Code 2374, OEM Code 197, OEM Code 3714, SPN 2058 – FM14.																							
OE	M Code 1	197, UEM Code	e 3714,	SPN	2058 -	- ⊢M14	•																
								~	0/6 :														
								9/1	6/24			_					0101:	.==			_		
		EMPLOYEE'S FULL	_ NAME (I	PLEASI	= PRINT)			DATE	=				-1-1-1	EMP	LOYEE'S	SIGNATI	JKE					