

<b>RTR Services Inc.</b> <b>HEAVY TRUCK</b> <b>CONDITION REPORT</b>		<b>RTR #:</b> 4081176 <b>ACCOUNT NUMBER:</b> <b>ACCOUNT NAME:</b>
---	---	---

YEAR: 2016	MILES: 596,251.7	VIN#: 1XPBD49X7GD281185
MAKE: Peterbilt	GVW: 50000	LICENSE: YP91972
MODEL: 579	WHEELBASE: 21'	COLOR: EXTERIOR: Blue
ENGINE: Cummins ISX15	HP:	KEYS: IGNITION: <input type="checkbox"/> YES <input type="checkbox"/> NO
TRANS: 10 Spd Manual	FUEL: <input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL	ANTIFREEZE TESTED: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
DOES MOTOR RUN? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	CAN IT BE DRIVEN? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	COLLISION DAMAGE? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

**PHYSICAL APPEARANCE**

		GD	FR	PR	N/A	COMMENTS	OPTIONS
<b>BODY</b>	FRONT BUMPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR STEERING <b>BRAKES</b> <input checked="" type="checkbox"/> AIR <input type="checkbox"/> HYD <input checked="" type="checkbox"/> PWR LOCKS <input checked="" type="checkbox"/> PWR WINDOWS <input type="checkbox"/> PWR SEATS <input checked="" type="checkbox"/> PWR MIRRORS <input checked="" type="checkbox"/> AIR CONDITIONER <input checked="" type="checkbox"/> AIR RIDE SEAT D/P <input checked="" type="checkbox"/> AIR RIDE SUSPENSION <input type="checkbox"/> CONV. 5 <sup>TH</sup> WHEEL <input checked="" type="checkbox"/> SLIDING 5 <sup>TH</sup> WHEEL <input type="checkbox"/> AM FM RADIO <input type="checkbox"/> TAPE / CD / CB? <input checked="" type="checkbox"/> SLEEPER SIZE? 6ft <input checked="" type="checkbox"/> ELECTRICAL PIGTAIL <input checked="" type="checkbox"/> GLAD HANDS <b>FUEL TANKS</b> <input type="checkbox"/> SINGLE GAL <input checked="" type="checkbox"/> DUAL GAL 100 <input checked="" type="checkbox"/> MUD FLAPS <b>WHEELS</b> <input checked="" type="checkbox"/> ALUMINUM <input type="checkbox"/> STEEL <input type="checkbox"/> BUD <input type="checkbox"/> SPOKE <input checked="" type="checkbox"/> EXHAUST S/D? S <b>SUSPENSION</b> <input checked="" type="checkbox"/> AIR <input type="checkbox"/> SPRING <input type="checkbox"/> PAD <input type="checkbox"/> TANDEM AXLE <input type="checkbox"/> ENGINE BRAKE <input type="checkbox"/> TOOL BOX <input type="checkbox"/> LIFT/TAG AXLE <input type="checkbox"/> WET KIT <input checked="" type="checkbox"/> PTO/ Fluid box
	HEAD LIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	HOOD	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Damage to both d/s and p/s above wheel	
	TURN SIGNALS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	GRILL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	D FRONT FENDER	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	some damage	
	D DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	D SLEEPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	REAR BUMPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	TAIL LIGHTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
REAR PANEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
P FRONT FENDER	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Damage missing mirror on side also		
P FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
P SLEEPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
TOP	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
<b>TIRES</b>	D FRONT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	70 % 295/75R22.5 SIZE:	
	D REAR A1 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	40/40 % 295/75R22.5 SIZE:	
	D REAR A2 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	40/40 % 295/75R22.5 SIZE:	
	P FRONT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	70 % 295/75R22.5 SIZE:	
	P REAR A1 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	40/40 % 295/75R22.5295/75R22.5 SIZE:	
	P REAR A2 (S/D?)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	40/40 % SIZE:	
	SPARE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	
<b>GLASS</b>	WINDSHIELD	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	D FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	REAR WINDOW	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	P FRONT DOOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	MIRRORS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Missing passenger front over the hood	
<b>INTERIOR</b>	DASH	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	DOOR PANELS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	SEAT(S)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	CARPET	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	HEADLINER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
SLEEPER	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
<b>MECHANICAL</b>		GD	FR	PR	UKN	N/A	COMMENTS:
	ENGINE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	TRANSMISSION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	CLUTCH	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	DIFFERENTIALS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	BRAKES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	FRONT END	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	REAR END	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
BATTERY/ELECTR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		

**This is Not a Mechanical Inspection Report / It is a Visual Inspection Only - DEF & DPF Functions Not Verified, Buyer Responsible to Validate.**

COMMENTS: Mileage unverified. Right rear on passenger side inside hub appears oily. Appears low on coolant.

8-22-24

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
<small>By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.</small>		

**RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421**

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107