	D=0											D.T.D. //	4004					
RTR Services Inc. BOX TRUCK									RTR #: 4081489 ACCOUNT NUMBER:					189	9			
CONDITION REPORT							1	ACCOUNT NAME:										
YEAR: 2014		2014		MIL	.ES	152, 02	152, 027			VIN#: 1FDWE3FL2EDA56869								
MAKE: F		Ford	ord		W:	10,050 BOX HEI		X HEIGH	BOX LENGTH				BOX WIDTH					
MODEL:		E350		WH	WHEELBASE:		138		COLOR: EXTERIOR: White				INTERIOR: Gray					
ENGINE:		5.4L		HP					EYS: IGNITION: 🛛 YES 🗌 NO 🔹 DOOR: [⊠ YE							
TRANS: Automatic			Γ			GAS [l l	ANTIFREEZE TESTED: ☐ YES ☒ NO					RATING:				
DOES MOTOR RUN? ⊠ YES □ NO CAN IT BE DRIVEN? ⊠ YES □ NO COLLISION DAMAGE? ⊠ YES ⊠ NO PHYSICAL APPEARANCE													⊠ NO					
			GD	FR	DD	N/A	COM	MENTS	AL APPEA	AKAN	NCE)DTIC	NIC SINC	
	FRONT	BUMPER			PR 🖂	IN/A			large den	arge dent					OPTIONS PWR STEERING			
	HEAD LIGHTS HOOD TURN SIGNALS													BR	BRAKES			
ВОДУ																		
	GRILL					ΙH	Hole	and Cracl	ks					\neg	PWR L		3	
	D FRONT FENDER			\boxtimes					-						PWR W			
	D DOOR				\boxtimes		Hinge	s broken	& exterio	or rus	sted and s	crached		\dashv \Box	PWR S			
	D BOX REAR BUMPER			\boxtimes										$- \square$	PWR M			
	TAIL LIGHTS			\boxtimes													AT D/P	
	REAR PANEL																JSPENS	ON
	P FRONT FENDER P FRONT DOOR			\boxtimes											AM FM TAPE /			
	P BOX			\boxtimes										ᅥᆸ	SLEEP			
	TOP			\boxtimes													ENT ROC)F
TIRES	D FRONT							245/75R1 245/75R1							E-TRA			
	D REAR A1 (S/D?) D REAR A2 (S/D?)						10 %	245/75K1	SIZE:					┦뭄	BOX D	_	LIGHT	
	P FRONT `				\boxtimes		20 %	245/75R1							EL TANK	S		
	P REAR A1 (S/D?)				\boxtimes		10 %	245/75R1									AL	
	P REAR A2 (S/D?) SPARE							<u>%</u> %	SIZE:					\dashv_{\boxtimes}			۱L	_
	WINDSHIELD D FRONT DOOR REAR WINDOW P FRONT DOOR MIRRORS							76 SIZE.							WHEELS			
GLASS				\boxtimes											☐ ALU		JM	
													_ ⊠ STEEL □ BUD					
INTERIOR	DASH DOOR PANELS SEAT(S) FLOORING HEADLINER SLEEPER BOY			\boxtimes													/D? <u>S</u>	
							Middle seat only has back rost missing seat			SU	SUSPENSION							
							Wildu	Middle seat only has back rest, missing seat.					_	│ │ │ AIR │ │ │ SPRING				
				\boxtimes)		
_														TANDE				
	вох		GD	FR	PR	UKN	N/A	COMM	ENTS:					$\dashv \vdash$	ENGIN TOOL I		1NE	
	ENGIN			\boxtimes											LIFT/T/		(LE	
AL.	TRANSMISSION			\boxtimes										\dashv \Box	RAMP	A T.C		
MECHANICAL	CLUTCH DIFFERENTIALS													$\exists \exists$	LIFT G	AIE		
	BRAKES													╛				
	FRONT END																	
	REAR END BATTERY/ELECTR							Dead						$\exists \exists$				
		GERATION						Deau						ᅥ旹				
COMMENTS: Mileage unverified. Working on getting battery replaced. Roll up door broken, very hard to open with wire.																		
	9/13/2024																	
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.																		