RTR Services Inc.		RTR#: 4083397	
GENERAL EQUIPMENT		ACCOUNT	
CONDITION REPORT			ACCOUNT NAME:
YEAR:	2021		
MAKE:	Morbark	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	1821	☑ OPERATIONA	L
SN:	4S8SZ1613MW02645	□ NON OPERATIONAL	
POWER:	Cat Engine	UNTESTABLE	
DESCRIPTION: Brush Chipper			
SHOT / COUNT / HOUR: 1207.55			
NOTES / COMMENTS: Hours unverified. The wires are cut for the tail lights and the lights are missing. Dents/ dings and scratches throughout machine. Unit does start up and run, but cannot fully throttle up due to the clutch being bad.			
	ervices Inc.		RTR#:
	EQUIPMENT		ACCOUNT
	ON REPORT		ACCOUNT NAME:
YEAR:			
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		OPERATIONA	
SN:		□ NON OPERAT	
POWER:		UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR: NOTES / COMMENTS:			
	ervices Inc.		RTR#:
GENERAL EQUIPMENT			ACCOUNT
	ON REPORT		ACCOUNT NAME:
YEAR:			I
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		OPERATIONA	
SN:		☐ NON OPERAT	
POWER:		UNTESTABLE	
DESCRIPTION:	LIQUID.		
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			
8/23/2024 EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE Project the body setting all information contained within this concil to be been of my knowledge at three and			
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.			