RTR Services Inc. TRAILER CONDITION REPORT											RTR #: ACCOUNT NUMBER: ACCOUNT NAME:					4083680-04				
YEAR: 2022				BODY TYPE:		Dry Van					X2XNG000714									
MAKE: Atro			LICI		ENSE:				STATE:				TAGS: MN:				YR:			
MODEL:			COI		OLOR:	EX	TERIOR:	W	White				INTERIOR:		Αlι	ıminum				
LENGTH: 53'			WIDTH:		WIDTH:				HEIGHT:							GVW : 68,000				
HITCH: GOOSE N		ECK	☐ PINTLE 🖂 5		∑ 5 TH	WHEEL PIN 1			7/8" BALL 🔲 2" B		BALL	L ☐ 2 5/16" BA		ALL						
	IS IT RO	AD READY?	⊠ YE	S	□ №		COLLISION DAMA					⊠ NC)	KEYS		☐ YES	⊠ NO)		
PHYSICAL APPEARANCE																				
	FRONT PANEL		GD	FR	PR	N/A	COM	COMMENTS										PTIONS DE SUSPE		
TIRES INTERIOR BODY	REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A2 (S/D?)						% % % % % %	SIZE: SIZE: SIZE: SIZE:	5/7522.5 5/7522.5						AIR BRAKES ELECTRICAL BRAKES HYD BRAKES SLIDER AXLE WHEELS BUD SPOKE STEEL ALUMINUM LIFT/TAG AXLE SPARE TIRE RACK REFIGERATION UNIT REEFER HRS TOOL BOX MUD FLAPS ROLL UP REAR DOOR LOADING RAMP BATTERY					
	P REAR A3 (S/D?)					\boxtimes	% SIZE:													
	SPARE		GD	FR	│ □ │ PR	UKN	% N/A	SIZE:		S:										
MECHANICAL	CLEAR SLIDEF REFRIC LANDII AIR HO	GHTS L LIGHTS ANCE LGT AXLES GERATION NG GEAR PSE/GLAD R PIGTAIL																		
CO	MMENTS	3: Unit has sci	ratched	l and	dents	hrougho	ut and	overall. A	ll tir	es are	poor.									
		EMPLOYEE'S FULI	L NAME (PLEAS	E PRINT)		9/	16/2024 DATE						EMP	PLOYEE'S SI	GNATI	JRE		_	
		By sig	nature ab	ove I d	o hereby	certify all info	ormation c	ontained with	in this	report to	be true a	and acc	curate to th	e best o	f my knowled	lge at p	resent.		_	