RTR Services Inc. TRAILER CONDITION REPORT											RTR #: 40830 ACCOUNT NUMBER: ACCOUNT NAME:					30-05			
YEAR: 2022					BODY TYPE:			Dry Van			VIN#: 3ELA6RX				00715				
MAKE: Atro			LICE		ENSE:				STATE:				TAGS: MN:				YR:		
MODEL:			COLO		OLOR:	EXTERIOR:		W	Vhite				INTERIOR:		Aluminum				
LENGTH: 53'				WIDTH:					HEIGHT:							GVW : 68,000			
HITCH: GOOSE N		ECK	☐ PINTLE ⊠ 5 ^T		⊠ 5 TH	WHEEL PIN 17			7/8" BALL		BALL	. 🔲 2 5/16" BA		ALL					
	IS IT RO	AD READY?	⊠ YE	S	□ №		COLLISION DAMA			AGE? ☐ YES 🛛 🖾 N		⊠ NC)	KEYS		☐ YES	⊠ NC)	
PHYSICAL APPEARANCE																			
	FRONT PANEL		GD	FR	PR	N/A	COM	COMMENTS										PTIONS	
TIRES INTERIOR BODY	REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A2 (S/D?)		000000000000000000000000000000000000000				% % % % % % %	% SIZE: 295 % SIZE: 295 % SIZE: % SIZE: % SIZE: % SIZE: 295 % SIZE: 295			5						SPRING AIR BR ELECT HYD BI SLIDEF SELS STE ALU LIFT/T/A SPARE REFIGE REEFE TOOL E ROLL U	RICAL BR. RAKES RAXLE OKE EL IMINUM AXLE ETIRE RACE ERATION L R HRS BOX LAPS JP REAR I	SION AKES CK JNIT
					□														
MECHANICAL	CLEAR SLIDEF REFRIC LANDII AIR HO	IGHTS L LIGHTS LANCE LGT R AXLES GERATION NG GEAR DSE/GLAD R PIGTAIL	G	FR N N N N N N N N N N N N N N N N N N N	PR	UKN	N/A	COMM	ENT	S:									
COMMENTS: Unit has scratched and dents throughout and overall. All tires are poor.																			
9/16/2024 EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE												_							
						certify all info	ormation c		in this	report to	be true a	and acc	curate to th		f my knowled				_