RTR Services Inc.						ħ		RTR #: 408370 ACCOUNT NUMBER:							8						
HEAVY TRUCK																					
CONDITION REPORT							ACCOUNT NAME:														
YEAR:		2018			LES	480,4	66	,	VIN#:	3A	AKJGLDR2JSJK3547										
MAKE:		Freightliner		GV	GVW : 52,00		0 LICENSE:					ST: T		AGS:	MONT	Н		YR:			
MODEL:		Cascadia 125		WI	WHEELBASE:				CC	COLOR: E		XTERIOR: White		INTE		RIOR: Gray		Gray/	Tan		
ENGINE:		DD15 Diesel		HP	HP		BODY TYPE:		Sleepe	Sleeper		KEYS: IGNITION: [⊠ YES	□NO	DOOR: YES □ NO					
TRANS:		Automatic			EL: [GAS	⊠ DIESE	L .	ANTIFREEZE		TESTED: 🗌 Y		YES [YES ⊠ NO		RATIN	G:				
DOES M		OTOR RUN?	R RUN?		□ NC)	CAN IT BE DRIV				□ NO		СО	COLLISION DAMA		MAGE?] YES	⊠ l	10	
PHYSICAL APPEARANCE																					
ВОДУ			GD	FR	PR	N/A	COMI	MENTS											IONS		
	_	BUMPER		\boxtimes												_	ERING	i			
	HEAD LIGHTS HOOD TURN SIGNALS				I H	I B									_ BK	BRAKES ⊠ AIR					
				\boxtimes												HYD					
	GRILL																_				
	D FRONT FENDER D DOOR			\boxtimes	\parallel										_ =	PWR WINDOWS PWR SEATS					
	D SLEEPER					ΙH										☐ PWR SEATS ☐ PWR MIRRORS ☐ AIR CONDITIONER					
	REAR BUMPER			X		╅															
	TAIL LIGHTS			\boxtimes																	
			<u> </u>		무	+ 무											☐ AIR RIDE SUSPENSION ☐ CONV. 5 TH WHEEL				
	P FRONT PENDER P FRONT DOOR			\boxtimes												$ $ \boxtimes					
	P SLEEPER		ä		\Box																
	TOP			\boxtimes																	
TIRES	D FRONT][40 % 295/75R22.5 SIZE:								_ =					
	D REAR A1 (S/D?) D REAR A2 (S/D?)				\boxtimes			2020 % 295/75R22.5 SIZE: 10/20 % 295/75R22.5 SIZE:									☐ ☐ GLAD HANDS				
	P FRONT							2 % 295/75R22.5 SIZE:									FUEL TANKS				
	P REAR A1 (S/D?)				\boxtimes			20/15 % 295/75R22.5 SIZE:									SINGLE GAL				
	P REAR A2 (S/D?)						20/10	20/10 % 295/75R22.5 SIZE:									DUAL GAL				
ss	WINDS	-		믐			% SIZE:								│						
	D FRONT DOOR																	ALUM	INUM		
LAS	REAR WINDOW					\boxtimes											_	STEEL	-		
၂ ၂ P FRO		NT DOOR		\boxtimes											☐ BUD ☐ SPOKE						
	MIRRO DASH	KS	∺		H	$+ \vdash$										\dashv \sqcap			⊏ TS/D?		
Χ	DOOR													ISION							
RIO	SEAT(S)				\boxtimes		D/S v	D/S very stained / worn								\boxtimes					
INTER	CARPET																	SPRIN	IG		
_	HEADLINER SLEEPER														\dashv	_	PAD NDFM	AXLE			
	OZZZ.	GD	FR	PR	UKN	l N/A	COM	VIENTS	S :									BRAKE			
١.	ENGIN				\boxtimes						water pu	mp rep	lace	d.		TO	OL BC	X			
₹	TRANSMISSION CLUTCH					lп		Serpe	entine	belt is b	rok	ken.				\dashv	HE	T/TAG	AXLE		
MECHANICAL																ᅱᆷ		T KIT	AALL		
	DIFFERENTIALS			\boxtimes																	
	BRAKES FRONT END REAR END																				
																$\exists \exists$					
	BATTE	BATTERY/ELECTR			\boxtimes				equired jump.												
COMMENTS: Mileage unverified. Several of the tires are missing chunks of tread, may be low on air.																					
	8/28/2024																				
		EMPLOYEE'S FULL					-	DATI	E	_	_					SIGNATUI				_	
							information of	ontained w	ithin this	report to be	e true	e and accura	ate to the	best of	f my knowl	edge at pre	esent.				