RTR Services Inc. EXCAVATOR WHEEL/TRACK						RTR #: 408384 ACCOUNT NUMBER: ACCOUNT NAME:														
CONDITION REPORT					<u>1979-9</u>)															
YEAR: 2008				VIN/SN:		30079														
MAKE: Komatsu					HEEL [L 🛛 TRACK														
MODEL: PC308US						EXTERIO						lack								
ENGINE:																				
TRANS: Hydrostatio		;			FUEL: 🛛 DI					EZET	1				-	TING:				
HRS: 11,951					DOES	S IT RUN					UNK	(CAN IT	F BE D	RIVEN?	\boxtimes	YES		NO	
								IYSICA		EARAI	NCE									
MECHANICAL INTERIOR GLASS TIRES BODY	MIRROR DASH/G DOOR P SEAT CARPET CONTRO	GHTS GNALS PANEL LIGHTS ANEL HTS GNALS F PANEL IGHTS GNALS F PANEL IGHTS (S/D?) F (S/D) F (S/D) F (S/D) F (S/D) F (S/D) F (S/D) F		F × × × × × × × × × × × × × × × × × × ×			COMN	<u>%</u> % % % width		ZE: ZE: ZE: ZE:							TINT AIR HEA AIR AIR TAP CD I BUC QUIU HYD	COSI FED G CONI TER RIDE FM R FM R FM R FM R FM R FM R FM R FM R	ER OUPLI MB	NER
INAL		UNDERCARRIAGE BRAKES FRONT END REAR END BATTERY/ELECTR		\boxtimes																
ВĊ	FRONT			\boxtimes																
Σ								New	09/202	-										
C		Hours unver	ified.						551202	. .										
								1/24												

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107