RTR Services Inc. TRAILER											RTR #: 4083881 ACCOUNT NUMBER:										
CONDITION REPORT YEAR: 2013				BODY	TYPE:	Conestoga			ACCOUNT NAI				26601								
MAKE: Utility					ENSE:	Concatoga			STATE:		1011-32400		TAGS: MN:					Τ,	YR:		
MODEL: FS2CHA				COLOR:		EXTERIOR: W		WI	hite/Blk				INTERIOR:		_						
LENGTH: 48ft			WIDTH:			9ft			HEIGHT:		11 1/2 ft					GVW : 73,000 lbs		00 lbs			
		☐ GOOSE N	ECK	□Р	PINTLE 🛛 5 TH		WHEEL PIN 1] 1 7	7/8" BALL		☑ 2" BALL		☐ 2 5/16" BA		" BA	ALL				
IS IT ROAD READY? 🛛 YES			S	□ №		COLLISION DAMA			AGE? YES N			⊠ No	O KEYS			: ☐ YES ☐ NO					
PHYSICAL APPEARANCE																					
	FRONT PANEL		GD	FR	PR	N/A	COMMENTS										OPTIONS				
TIRES INTERIOR BODY	HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A3 (S/D?) P FRONT P REAR A1 (S/D?)						% % % % % %	SIZE: SIZE: SIZE: SIZE:	295 295	/75R 2 /75R 2 /75R 2	2.5							SPRIM AIR B ELEC HYD B SLIDE EELS ST AL LIFT/A REFIC REEF TOOL MUD ROLL	NG SI BRAK BRAK BRAK JD POKE EEL LUMIN TAG A EE TIF EER H BO) FLAF LUP I	AL BRAI KES KLE NUM AXLE RE RACK ATION UN	ION KES
	P REAR A3 (S/D?) SPARE					\boxtimes	%	SIZE:													
MECHANICAL	CLEAR SLIDEF REFRIC LANDII AIR HO	GHTS L LIGHTS ANCE LGT R AXLES GERATION NG GEAR DSE/GLAD R PIGTAIL	GD		PR		N/A	COMMI	ENT	S:											
COMMENTS: Mid sections of the tarp brackets appears to be out of place/detached. Tarp doesn't fully function properly.																					
09/12/2024																					
		EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.																			