RTR Services Inc.										RTR #: 409144					J1			
BOX TRUCK CONDITION REPORT				and and				Α	ACCOUNT NUMBER:									
YEAR:		2019	PUKI		ES	169,251			VIN#: 1HTMKTAL2KH457860									
		International		GVW:				OX HEIGH		.	BOX LENGTH		10	BOY	WIDTH			
		4400 Tool Tru			WHEELBASI						White					Gray		
ENGINE:		Cummins L9		HP 350						EYS: IGNITION: X YES NO · DOOR		DOOR:				Jiuy .		
TRANS:		Automatic					GAS ⊠ DIESEL		NTIFREEZE TESTED: ☐ YES ☒ NO			RATING:						
		OTOR RUN?	⊠ YES				CAN IT BE DRIVE						SION DAMAGE?			YES NO		
							AL APPE	ARAN										
			GD	FR	PR	N/A	COMMENTS						OPTIONS					
ВОДУ	_	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS GRILL D FRONT FENDER		\boxtimes											PWR S	STEE	RING	
	HOOD			\boxtimes										⊠ AIR				
	_			\boxtimes											☐ HYD PWR LOCKS			
	D FRO													$-\mid\boxtimes$	PWR V			
	D DOO	D DOOR		\boxtimes											PWR S			
	D BOX REAR	D BOX		\boxtimes											PWR N		JRS FIONER	
	TAIL L	TAIL LIGHTS		\boxtimes											AIR RI	DE S	EAT D/P	
		REAR PANEL P FRONT FENDER		\boxtimes											AIR RI AM FN	_	USPENSION	
	P FRO	P FRONT DOOR		\boxtimes											TAPE	CD/	CB? <u>CD</u>	
	P BOX			\boxtimes										⊢믐	SLEEF		ENT ROOF	
TIRES		D FRONT			\boxtimes		10 %		IZE:						E-TRA			
		D REAR A1 (S/D?) D REAR A2 (S/D?)					45/4	5 % %	SIZE:						_	-	LIGHT	
	P FRO	P FRONT [15 %		IZE:						EL TAN		•	
		P REAR A1 (S/D?)		\boxtimes			45/4		SIZE:								GAL <u>100</u>	
	P REAR A2 (S/D?)							<u>%</u> %	SIZE:					\dashv_{\boxtimes}			AL S	
GLASS	_	WINDSHIELD D FRONT DOOR REAR WINDOW												_	HEELS			
	REAR														☐ ALUMINUM ☐ STEEL ☐ BUD ☐ SPOKE			
ี อี	P FRONT DOOR			\boxtimes														
	DASH			\boxtimes										\dashv_{\bowtie}			S/D? S	
RIOR		DOOR PANELS SEAT(S) FLOORING HEADLINER		\boxtimes											SPENSI		_	
				\boxtimes											⊠ AIR □ SPI			
INTERI	HEADL			\boxtimes	ļ □										□ PAI	D		
_	SLEEPER BOX													ᅱ님	TANDI ENGIN			
MECHANICAL	G			FR	PR	UKN	N/A	COMM	ENTS:						TOOL	вох		
		ENGINE TRANSMISSION		\boxtimes										⊢믐	LIFT/T	AG A	XLE	
	CLUTC	CLUTCH													LIFT G	ATE		
	DIFFE	DIFFERENTIALS BRAKES		\boxtimes										⊢믐				
	FRONT	FRONT END												=				
	REAR	REAR END		\boxtimes														
	REFRI	GERATION			\square													
COMMENTS: Mileage unverified. Includes: Cummins Onan generator w/ 3,764 hours. Decal wrap was removed from side panels and there is glue																		
residue. Janis will be working to get the battery replaced.																		
							Q	/26/2024	L									
		EMPLOYEE'S FUL						DATE					PLOYEE'S					
		By sig	gnature abo	ove I do	hereby	certify all in	nformation	contained with	nin this report	t to be t	rue and accura	ite to the best	of my know	ledge at p	oresent.			