RTR Services Inc. TRAILER											RTR #: 4093182-01 ACCOUNT NUMBER: ACCOUNT NAME:								
CONDITION REPORT YEAR: 2016					BODY	TYPE:	Reefer			VIN#: 1GRAA0623GW7028				702854					
MAKE: Great Dane						ENSE:	Reciei			STATE:			TAGS: MN:					YR:	
MODEL: Reefer Trailer						OLOR:	EXTERIOR: W			hite					TERIOR:				
LENGTH: 53ft				WIDTH:		10ft			HEIGHT: 13ft6in		6in				GVW: 68,000lbs				
HITCH: GOOSE N		ECK	☐ PINTLE ⊠ 5 TH			WHEEL PIN						2 5/16" B	2 5/16" BALL		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
IS IT ROAD READY? ⊠ YES			s	□ NO	Ī	COLLISION DAMA			AGE? YES N			⊠ No	IO KEYS		 3:	☐ YES	⊠ NO		
PHYSICAL APPEARANCE																			
GD I			FR	PR	N/A	COM	MENTS						OPTIONS						
RES INTERIOR BODY	REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A3 (S/D?)		000000000000000000000000000000000000000				Scratched									□ AIR BRAKES □ ELECTRICAL BRAKES □ HYD BRAKES □ SLIDER AXLE □ BUD □ SPOKE □ STEEL □ ALUMINUM □ LIFT/TAG AXLE □ SPARE TIRE RACK □ REFIGERATION UNIT □ REFER HRS 18,836 □ TOOL BOX □ MUD FLAPS □ ROLL UP REAR DOOR □ LOADING RAMP			
MECHANICAL	P REAF P REAF P REAF SPARE TAIL LI SIGNAI CLEAR SLIDER REFRIC LANDIN AIR HO	R A1 (S/D?) R A2 (S/D?) R A3 (S/D?))				% 30	SIZE: 295 SIZE: 295 SIZE: 295 SIZE: COMMI	ENT	S:	up and	dow	n				BATTER	T	
COMMENTS: Reefer hours unverified. Main airtank has a rust hole creating air leak. ABS brake box broken off bracket.																			
11/18/24																			
		EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.																	