RTR Services Inc.													RT	R #:	409340	2-03				
TRAILER CONDITION REPORT											ACCOUNT NUMBER: ACCOUNT NAME:									
YEAR: 2018				BODY	TYPE:	Flatbed			VIN#: Unverifi											
MAKE: Custom Max				LICENSE:					STA	STATE:			TAG	TAGS: MN:			YR:			
MODEL: Low Maxx SST2			C	OLOR:	EXTERIOR: B			lack	lack			INTERIOR:								
LENGTH: 53'				WIDTH:					HEIGHT:					GVW:						
			INTLE	5 [™]	-			7/8" BALL				2 5/16" B								
IS IT ROAD READY? ☐ YES │ ☑ NO │ COLLISION DAMAGE? │ ☐ YES │ ☑ NO │ KEYS: │ ☐ YES │ ☑ NO │ PHYSICAL APPEARANCE														0						
	FRONT PANEL HITCH		GD	FR 🖂	FR PR N/A □ □			COMMENTS									OPTIONS AIR RIDE SUSPENSION			
вору				\boxtimes													SPRING	SUSPE		
	D SIDE PANEL SIDE DOOR (S)																AIR BR	AKES RICAL BF	AKES	
	REAR PANEL					\boxtimes										\boxtimes	HYD BF	RAKES	(AILE	
	REAR DOOR (S) P SIDE PANEL																SLIDER	AXLE		
	REAR BUMPER														UHEELS □ BUD					
	TOP			\boxtimes													SPO			
NTERIOR	FLOOR D SIDE PANELS																⊠ STE			
	FRONT PANEL					\boxtimes										☐ LIFT/TAG AXLE				
	P SIDE PANEL CARGO RAILS					\boxtimes											_	TIRE RA	_	
=	CEILING					\boxtimes											_	R HRS		
ES.	D FRONT						%	SIZE: 235		:/D74 E							TOOL E	_		
	D REAR A1 (S/D?) D REAR A2 (S/D?)							SIZE: 23									MUD FLAPS□ ROLL UP REAR DOOR			
	D REAR A3 (S/D?)					\boxtimes	%	SIZE:								\boxtimes	_	NG RAMP)	
TIRES	P FRONT P REAR A1 (S/D?)						% % 80	SIZE:		5/R71.5							BATTE	RY		
	P REAR A2 (S/D?) P REAR A3 (S/D?) SPARE						% 80 SIZE: 235/75/R71.5 % 80 SIZE: 235/75/R71.5													
					□ □ □ ⊠ % SIZE: □ □ □ □ % 80 SIZE: 235/75/R71.5															
			GD	FR	PR	UKN	N/A	COMM												
HANICAL	TAIL LIGHTS SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION LANDING GEAR			\boxtimes																
				\boxtimes																
Ι¥				\boxtimes																
MEC								Rusted												
2	AIR HOSE/GLAD			\boxtimes																
CO	ELECTR PIGTAIL DMMENTS: Vin unvertised But			et all	over tr	ailor I a	rge wek	de over d	am.	ago and	orack	rs of f	roamo	towar	de front o	f trai	lor			
COMMENTS: Vin unverified,. Rust all over trailer, Large welds over damage and cracks of freame towards front of trailer.																				
9/26/24																				
		EMPLOYEE'S FULI			-	and the all to		DATE	: 4la :			and as			LOYEE'S SIC				_	