RTR Services Inc. TRAILER CONDITION REPORT											RTR #: 4093514 ACCOUNT NUMBER: ACCOUNT NAME:						1-02		
YEAR: 2022			/1 (1		BODY	TYPE:	Cargo			VIN#: 53FBE1429NF071			71570						
MAKE: Covered Wag		on		LICENSE:				STATE:			TAGS		S: MN:			YR:			
MODEL: CW7X14TA2				COLOR:		EXTERIOR: B		BI	ack		INTERIOR:								
LENGTH: 14 Ft			WIDT		WIDTH:				HEIGHT:				GVW:						
HITCH: ☐ GOOSE		☐ GOOSE N	ECK	□ PI	PINTLE 5 TH		WHEEL PIN			7/8" BALL 🛛 2" BALL			☐ 2 5/16" BA		BALL	ALL			
IS IT ROAD READY? 🛛 YES					□ NO		COLLISION DAMA			.GE? YES NO			KEY	S:	☐ YES	⊠ NO			
PHYSICAL APPEARANCE																			
GD F			FR	PR	N/A	COMI	COMMENTS									OPTIONS			
ВОДУ	FRONT PANEL HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL REAR BUMPER						Dented/holes all over body									SPRING SUSPENSION AIR BRAKES ELECTRICAL BRAKES			
							HYD Not aligned							HYD BR SLIDER HEELS	YD BRAKES LIDER AXLE :LS] BUD				
	TOP															☐ SPOKE			
FRONT		PANELS PANEL PANEL												☐ STEEL ☑ ALUMINUM LIFT/TAG AXLE SPARE TIRE RACK PEFICEPATION UNIT					
_	CARGO RAILS CEILING															┪╏	REFIGERATION UNIT		
TIRES	D FRONT D REAR A1 (S/D?) D REAR A2 (S/D?) D REAR A3 (S/D?) P FRONT P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?) P REAR A3 (S/D?) SPARE						% 5 SIZE: ST205/75R15								TOOL BOX MUD FLAPS ROLL UP REAR DOOR LOADING RAMP BATTERY				
			GD	FR	PR	UKN	N/A	COMM	ENT	'S:						╗			
MECHANICAL	CLEAR SLIDEF REFRIC LANDIN AIR HO	GHTS L LIGHTS ANCE LGT R AXLES GERATION NG GEAR PSE/GLAD R PIGTAIL																	
СО	MMENTS	3: The trailer h	as var	ious c	lents, d	dings, an	d punc	tures thro	ugh	out. B	rakes	do no	t work	•					
		EMPLOYEE'S FULL	NAME (PLEASI	E PRINT)		12	2-9-24 DATE						EMF	PLOYEE'S S	IGNAT	URE		
						certify all info	ormation c	ontained with	n this	report to	be true a	and acci	urate to th						