RTR Services Inc. TRAILER CONDITION REPORT										RTR #: 4093757 ACCOUNT NUMBER: ACCOUNT NAME:							
YEAR: 2010				BODY T			E: Reefer			VIN#: 1UYVS2532AU			2AU0	18493			
MAKE: Utility				LICENSE:					STATE:			TAGS: MN:		YR:		YR:	
MODEL: 3000R			СО		OLOR:	: EXTERIOR		Whi	White		INTERIOR:		White / Aluminum				
LENGTH: 53'		53'			WIDTH:					HEIGHT:					GVW:		
HITCH: GOOSE N		ECK	☐ P	NTLE	<b>⊠</b> 5 <sup>™</sup>				B" BALL								
	IS IT RO	AD READY?	⊠ YE	S	□ NO			ISION DA				⊠ NC	)	KEYS	<b>i</b> :	☐ YES	⊠ NO
							F	HYSICAL	APPI	EARANCE							
	FRONT PANEL		GD	FR	PR	N/A	COMMENTS Damage										TONS SUSPENSION
ВОДУ	HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL REAR BUMPER						Dama	ge									SUSPENSION
					$\boxtimes$		Dings   ☐ AIR BRAKES ☐ ELECTRICAL BI ☐ HYD BRAKES										
														-			
ш				$\boxtimes$		☐ ☐ Hard to close ☐ S							SLIDER A	-			
														WI	HEELS		
	TOP														☐ SPOKE		
NTERIOR	FLOOR			][	]										STEEL		
	D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING			$\boxtimes$											☐ ALUMINUM ☐ LIFT/TAG AXLE		
				$\boxtimes$												SPARE TIRE RACK	
≤				$\boxtimes$												<ul><li>☑ REFIGERATION UNIT</li><li>☑ REEFER HRS 22,730</li></ul>	
S	D FRONT D REAR A1 (S/D?) D REAR A2 (S/D?) D REAR A3 (S/D?) P FRONT P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?)						%	% SIZE: % 50 SIZE: 295/75R22.5 % 50 SIZE: 295/75R22.5								TOOL BO	
																<ul><li></li></ul>	
							% 50 SIZE: 295/75R22.5 % SIZE:								LOADING RAMP		
TIRES							% SIZE:									BATTER	Y
				$\boxtimes$	$\parallel$	□ □ % 50 SIZE: 295/75R22.5 □ □ % 50 SIZE: 295/75R22.5											
						$\boxtimes$	% SIZE:										
	SPARE		GD	FR	PR	UKN	% N/A	SIZE:		•							
_	TAIL LI	-								•							
SIGNAL LIG CLEARANCI SLIDER AXL REFRIGERA LANDING GI AIR HOSE/G				$\boxtimes$											╏╏		
		RAXLES		$\boxtimes$													
								Hoses coming out of unit, but runs			ut runs	1					
	ELECTR PIGTAIL			$\boxtimes$													
COMMENTS: Hours unverified. Exterior of reefer has hole and other damage. Inspector stated reefer runs, but didn't want to run it too long considering disconnected hoses.																	
							9/2	26/2024									
		EMPLOYEE'S FULI By sid	,		-	certify all inf	ormation o	DATE ontained withi	n this re	eport to be true	and ac	curate to th		LOYEE'S SIGN			