RTR Services Inc. TRAILER CONDITION REPORT											RTR #: 4093811 ACCOUNT NUMBER: ACCOUNT NAME:									
YEAR: 2013			ZINI		BODY	TYPE:	Dump			VIN#: 5MADS3538				25581						
MAKE: MAC		MAC			LICENSE:					ST	ATE:		TAGS			:		١	/R:	
MODEL: 21B Smooth				COLOR:		EXTERIOR: A		Al	luminum				INTERIOR:		: Al	Aluminum		l e		
LENGTH: 35'			WIDTH:		WIDTH:				HEIGHT:							GVW : 126,000				
HITCH: GOOSE N		ECK	K PINTLE		⊠ 5 TH	WHEEL	PIN [17	7/8" BA	\LL	2" BALL		☐ 2 5/16" BA		BALL	ALL				
	IS IT RO	AD READY?		ES	⊠ NO		COLLISION DAMA						⊠ NC	O KEYS			S: YES 🗵		⊠ NO	
PHYSICAL APPEARANCE																				
	FRONT	GD	FR	PR	N/A	COM	MENTS							OPTIONS AIR RIDE SUSPENSION						
TIRES INTERIOR BODY	HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A3 (S/D?) P FRONT P REAR A1 (S/D?)		000000000000000000000000000000000000000				% % % % % % %	SIZE:	R24.5						W W	SPRING SUSPENSION AIR BRAKES ELECTRICAL BRAKES HYD BRAKES SLIDER AXLE WHEELS BUD SPOKE STEEL ALUMINUM LIFT/TAG AXLE SPARE TIRE RACK REFIGERATION UNIT REEFER HRS TOOL BOX MUD FLAPS ROLL UP REAR DOOR LOADING RAMP BATTERY				
	P REAR A3 (S/D?) SPARE					\boxtimes	% SIZE:] 🗆				
MECHANICAL	CLEAR SLIDEF REFRIC LANDII AIR HO ELECT	L LIGHTS ANCE LGT AXLES GERATION NG GEAR DSE/GLAD R PIGTAIL	GD		PR SS SS SS SS SS SS SS SS SS S		N/A	13 are r 2 missi	niss											
COMMENTS: Missing 8 tires. 2 additional side lights missing.																				
10/11/2024																				
		EMPLOYEE'S FULL By sig					ormation co	DATE ontained with	n this	report to	be true a	and acc	curate to th		PLOYEE'S :					