| RTR Services Inc. TRAILER CONDITION REPORT | | RTR #: | 4093823 |
|---|---|---|---|
| | | ACCOUNT NUMBER: | |
| | | ACCOUNT NAME: | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| YEAR: | 2014 | BODY TYPE: | Dry Van | VIN#: | 1UYVS2534EP881509 | | | | |
| MAKE: | Utility | LICENSE: | | STATE: | | TAGS: MN: | / | YR: | / |
| MODEL: | VS2DX | COLOR: EXTERIOR: | White | INTERIOR: | Brown/White | | | | |
| LENGTH: | 53' | WIDTH: | 8ft | HEIGHT: | 13ft | GVW: | 65,000lb | | |

HITCH: ☐ GOOSE NECK ☐ PINTLE ☒ 5TH WHEEL PIN ☐ 1 7/8" BALL ☐ 2" BALL ☐ 2 5/16" BALL

| IS IT ROAD READY? | ☒ YES | ☐ NO | COLLISION DAMAGE? | ☐ YES | ☒ NO | KEYS: | ☐ YES | ☒ NO |
|---|---|---|---|---|---|---|---|---|

## PHYSICAL APPEARANCE

| | | GD | FR | PR | N/A | COMMENTS |
|---|---|---|---|---|---|---|
| BODY | FRONT PANEL | ☐ | ☒ | ☐ | ☐ | |
| | HITCH | ☐ | ☒ | ☐ | ☐ | |
| | D SIDE PANEL | ☐ | ☒ | ☐ | ☐ | |
| | SIDE DOOR (S) | ☐ | ☐ | ☐ | ☒ | |
| | REAR PANEL | ☐ | ☐ | ☐ | ☐ | |
| | REAR DOOR (S) | ☐ | ☒ | ☐ | ☐ | Latch on P/S door is loose, does not close properly. |
| | P SIDE PANEL | ☐ | ☒ | ☐ | ☐ | |
| | REAR BUMPER | ☐ | ☒ | ☐ | ☐ | |
| | TOP | ☐ | ☒ | ☐ | ☐ | |
| INTERIOR | FLOOR | ☐ | ☒ | ☐ | ☐ | |
| | D SIDE PANELS | ☐ | ☒ | ☐ | ☐ | |
| | FRONT PANEL | ☐ | ☒ | ☐ | ☐ | |
| | P SIDE PANEL | ☐ | ☒ | ☐ | ☐ | |
| | CARGO RAILS | ☐ | ☐ | ☐ | ☒ | |
| | CEILING | ☐ | ☒ | ☐ | ☐ | |
| TIRES | D FRONT | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | D REAR A1 (S/D?) | ☐ | ☒ | ☐ | ☐ | % Slight wear SIZE: 295/75R 22.5 |
| | D REAR A2 (S/D?) | ☐ | ☒ | ☐ | ☐ | % Slight wear SIZE: 295/75R 22.5 |
| | D REAR A3 (S/D?) | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | P FRONT | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | P REAR A1 (S/D?) | ☐ | ☒ | ☐ | ☐ | % Slight wear SIZE: 295/75R 22.5 |
| | P REAR A2 (S/D?) | ☐ | ☒ | ☐ | ☐ | % Slight wear SIZE: 295/75R 22.5 |
| | P REAR A3 (S/D?) | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | SPARE | ☐ | ☐ | ☐ | ☒ | % SIZE: |

| | | GD | FR | PR | UKN | N/A | COMMENTS: |
|---|---|---|---|---|---|---|---|
| MECHANICAL | TAIL LIGHTS | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | SIGNAL LIGHTS | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | CLEARANCE LGT | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | SLIDER AXLES | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | REFRIGERATION | ☐ | ☐ | ☐ | ☐ | ☒ | |
| | LANDING GEAR | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | AIR HOSE/GLAD | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | ELECTR PIGTAIL | ☐ | ☐ | ☒ | ☐ | ☐ | Broken, held on by tape |

| OPTIONS | |
|---|---|
| ☒ | AIR RIDE SUSPENSION |
| ☐ | SPRING SUSPENSION |
| ☒ | AIR BRAKES |
| ☐ | ELECTRICAL BRAKES |
| ☐ | HYD BRAKES |
| ☐ | SLIDER AXLE |
| WHEELS | |
| ☐ | BUD |
| ☐ | SPOKE |
| ☒ | STEEL |
| ☐ | ALUMINUM |
| ☐ | LIFT/TAG AXLE |
| ☐ | SPARE TIRE RACK |
| ☐ | REFIGERATION UNIT |
| ☐ | REEFER HRS _____ |
| ☐ | TOOL BOX |
| ☒ | MUD FLAPS |
| ☐ | ROLL UP REAR DOOR |
| ☐ | LOADING RAMP |
| ☐ | BATTERY |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |

COMMENTS:

09/25/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.



The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107