CONDITION REPORT ACCOUNT NAME: YEAR: 2020 BODY TYPE: Dry Van VIN#: 1UYVS2531L7044407 MAKE: Utility LICENSE: STATE: TAGS: MN: MODEL: VS2DX COLOR: EXTERIOR: White INTERIOR: White		
MAKE: Utility LICENSE: STATE: TAGS: MN:		
	l va	
MODEL: VSZDA	YR:	
	ite / Aluminum	
HITCH: GOOSE NECK PINTLE 5TH WHEEL PIN 17/8" BALL 2" BALL 2 5/16" BALL	VVV.	
	☐ YES 🖾 NO	
PHYSICAL APPEARANCE		
GD FR PR N/A COMMENTS	OPTIONS	
HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANEL P SIDE PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A3 (S/D?) D REAR A3 (S/D?) SIDE PANEL SIDE SIDE PANEL SIDE PANEL SIDE SIDE SIDE SIDE SIDE SIDE SIDE SIDE	AIR RIDE SUSPENSION SPRING SUSPENSION AIR BRAKES ELECTRICAL BRAKES HYD BRAKES SLIDER AXLE EELS BUD SPOKE STEEL ALUMINUM LIFT/TAG AXLE SPARE TIRE RACK REFIGERATION UNIT REEFER HRS TOOL BOX MUD FLAPS ROLL UP REAR DOOR LOADING RAMP BATTERY	
SPARE		
GD FR PR UKN N/A COMMENTS:		
COMMENTS: Per inspector - Couldn't plug in to check electrical. Unit will be road ready once tires are replaced.		
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at pres		