	RTR S	Services Ind										53	3									
		HEAVY TRUCK					<u> </u>		D)		AC											
	CONDI	TION REPO		J				ACCOUNT NAME.														
YEAR:		2017	17		MILES		308				VIN#: 1XKZDP9X9			9HJ16	HJ161655							
MAKE:		Kenworth		G۷	GVW:			LICENSE:					ST:		TAGS:		MON	MONTH			YR:	
MODEL:		T880		WH	WHEELE		:				COLOR:		EXTERIOR:		Blue		INTERIO		R:		Gray	
ENGINE:		Cummins	HP			В	DDY TYPE: SI			eeper KEYS: IGNITION: X YE			: XES		•	DOOR: ⊠ YES □ NO						
1	TRANS:	Unknown	FU	EL: [GAS	S 🖂	DIESEL A			NTIFREEZE	TI	TESTED: ☐ YES ⊠ NO			Ю	RAT	ING	NG:				
	DOES M	NOTOR RUN? X YES			□ NO)	CA	N IT BE DRIV		VEN? XES		3	□ NO COLLI		LLIS	SION DAI	MAGE	?	□ Y	ES	⊠ NO)
							PHYSICAL			APPEARA	APPEARANCE											
		GD				N/	Α	COMMENTS										OPTIONS				
ВОБУ	FRONT BUMPER			\boxtimes														☐ PWR STEERING				
	HEAD I	LIGHTS		\boxtimes		[В		AKES □ AIR			
	TURN SIGNALS GRILL																					
				\boxtimes														_	PWR I		KS	
	D FRONT FENDER													_	☐ PWR WINDOWS							
	D DOO D SLEE		\boxtimes		-		Minor dents															
	REAR			H	1 2	,	mile done									╗	_			ITIONE	R	
	TAIL LI			\boxtimes				Dim									╗╒	-				
	REARI	PANEL NT FENDER					_										4 F				SUSPEI WHEEI	
	_	P FRONT DOOR		\boxtimes													╗				TH WHE	
	P SLEEPER			\boxtimes]	Dented	ł] /	AM FM RADIO			
TIRES	TOP D FRONT				무		_		%		SIZE:						┦ 듣				/ CB?	
	D REAR A1 (S/D?)					1 2			%		SIZE:						-				AL PIG	TAIL
	D REAL	D REAR A2 (S/D?) P FRONT P REAR A1 (S/D?) P REAR A2 (S/D?)			\boxtimes]	% % %			SIZE:						╗┎) (GLAD		NDS	
											SIZE:						_ F		TAN			
				H							SIZE:										EGAL_ BAL	
	SPARE					×]	% SIZE:						_								
ASS	WINDSHIELD D FRONT DOOR																w		ELS			
	_	REAR WINDOW P FRONT DOOR]											_	☐ AL ☐ STI		NOW	
GLA	1			\boxtimes										□ BUD								
	MIRRO	RS				 		D/S side mirror and casing broken								⊢	☐ SPOKE ☐ EXHAUST S/D?					
~	DASH	PANEI S		\boxtimes			_											EXHAUST S/D? JSPENSION				
RIOR	1	DOOR PANELS SEAT(S)		\boxtimes											┨ ॅ		AIR					
INTE	CARPE	CARPET				dirty													_ SP	RING	3	
≥	HEADL SLEEP						_	worn									┨		☐ PAD TANDEM AXLE			
	JEEEF	=:\	GD	FR			N	N/A COMME			ENTS:							-			RAKE	
MECHANICAL	ENGIN								Runs	rc	ough and no			hange)		□□] 1	TOOL.			
		TRANSMISSION CLUTCH DIFFERENTIALS		\boxtimes							ission shift play in ped		loose				┦ [_	_IFT/T NET k		AXLE	
	1								LOIS	<u> </u>	play III pec	aı					ᆔᆮ	_	V L	XI I		
		BRAKES		\boxtimes]]				
		FRONT END			\parallel									⊒ ⊑								
	1	RY/ELECTR		\boxtimes		-	j											j				
COMMENTS: Mileage unverified. Wear and tear on rear tires rear axles. Anti freeze is low. No visible oil or air leaks. Airbags did fill up and not											d not											
ble	ed down	•																				
10-16-2024																						
		EMPLOYEE'S FULL By sig					all info	ormation co	DA1		in this report to	be tr	ue and accura	ate to the		MPLOYEE'S						-
		2, 018	,		y						spo to	4			001	,	50 31	1200				_