

YEAR: 2023	MILES 227,548	VIN#: 1XKYDP9X9PJ225610
MAKE: Kenworth	GVW:	LICENSE:
MODEL: T680	WHEELBASE:	COLOR: EXTERIOR: Blue
ENGINE: Paccar MX-13 12.9L	HP:	BODY TYPE: Sleeper
TRANS: Automatic	FUEL: <input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL	KEYS: IGNITION: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO • DOOR: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
DOES MOTOR RUN? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	CAN IT BE DRIVEN? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	COLLISION DAMAGE? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

PHYSICAL APPEARANCE

	GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Missing	<input type="checkbox"/> PWR STEERING BRAKES <input checked="" type="checkbox"/> AIR <input type="checkbox"/> HYD <input checked="" type="checkbox"/> PWR LOCKS <input checked="" type="checkbox"/> PWR WINDOWS <input type="checkbox"/> PWR SEATS <input checked="" type="checkbox"/> PWR MIRRORS <input checked="" type="checkbox"/> AIR CONDITIONER <input checked="" type="checkbox"/> AIR RIDE SEAT D/P <input checked="" type="checkbox"/> AIR RIDE SUSPENSION <input type="checkbox"/> CONV. 5 TH WHEEL <input checked="" type="checkbox"/> SLIDING 5 TH WHEEL <input type="checkbox"/> AM FM RADIO <input type="checkbox"/> TAPE / CD / CB? <input checked="" type="checkbox"/> SLEEPER SIZE? <input checked="" type="checkbox"/> ELECTRICAL PIGTAIL <input type="checkbox"/> GLAD HANDS FUEL TANKS <input type="checkbox"/> SINGLE GAL <input checked="" type="checkbox"/> DUAL GAL <input checked="" type="checkbox"/> MUD FLAPS WHEELS <input checked="" type="checkbox"/> ALUMINUM <input type="checkbox"/> STEEL <input type="checkbox"/> BUD <input type="checkbox"/> SPOKE <input checked="" type="checkbox"/> EXHAUST S/D? S SUSPENSION <input checked="" type="checkbox"/> AIR <input type="checkbox"/> SPRING <input type="checkbox"/> PAD <input checked="" type="checkbox"/> TANDEM AXLE <input type="checkbox"/> ENGINE BRAKE <input type="checkbox"/> TOOL BOX <input type="checkbox"/> LIFT/TAG AXLE <input type="checkbox"/> WET KIT <input checked="" type="checkbox"/> MICROWAVE
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
TIRES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	50 % 295/75R22.5 SIZE:	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	50 % 295/75R22.5 SIZE:	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	50 % 295/75R22.5 SIZE:	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	50 % 275/80R22.5 SIZE:	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	50 % 275/80R22.5 SIZE:	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	50 % 275/80R22.5 SIZE:	
GLASS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
INTERIOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
MECHANICAL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Will not go into gear. Missing parts.	
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Runs with jump. Will need to be replaced.	

COMMENTS: Mileage unverified. Engine turbocharger is disconnected and leaking oil/coolant. Multiple engine connectors are unplugged. Leaks water from water pump. ABS system missing valve and is not capped.

10/14/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.		