GENERAL EQUIPMENT CONDITION REPORT		ACCOUNT ACCOUNT NAME:					
YEAR:	2020						
MAKE:	Cape Horn	🗌 YES 🖾 NO	EQUIPMENT WAS IN USE AT THE TIME OF R	ECOVERY			
MODEL:	31T						
SN:	FAB31382J920						
POWER:	Merc 350 (2)						
DESCRIPTION:	Outboard motors						
SHOT / COUNT / HOUR: 230.5/228.0							
NOTES / COMMENTS: Missing hour meter. Battery fair, has radar, 32 ft lonf, 8 ft wide, 3 in wide at stern. Props in fair condition. Boat is slightly dirty from prior use. Boat on top of trailer. No photo of odometer, full report in photo directory.							

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #: ACCOUNT ACCOUNT NAME:			
YEAR:						
MAKE:		🗆 YES 🗌 NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY			
MODEL:						
SN:						
POWER:						
DESCRIPTION:						
SHOT / COUNT / HOUR:						
NOTES / COMMENTS:						

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: ACCOUNT ACCOUNT NAME:			
YEAR:					
MAKE:		🗆 YES 🗌 NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:					
SN:					
POWER:					
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

11/7/24

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107