RTR Services Inc. EXCAVATOR WHEEL/TRACK CONDITION REPORT									RTR #: 410390 ACCOUNT NUMBER: ACCOUNT NAME:					05-01				
YEAR: 2023				VIN/S	N:	34NM12479												
MAKE: Bobcat				🗆 WI	HEEL [К											
MODEL: E88 R2					COLC	R: E	XTERIOR: White/Red INTERIOR: G							Gray				
ENGINE: D24					KEYS	: IGNI	FION: 🖂	ON: 🛛 YES 🗌 NO 🗌 N/A 🔸 DOOR: 🗌 YES 🖾 NO 🗌 N						A				
TRANS: Hydraulic					FUEL: 🛛 DI		ESEL 🗌	GAS	ANT	IFREEZ	ETES	TED: 🗌 YI	ES 🖾 NO	RA	TING:			
HRS: 443				DOES	IT RUN	? 🛛 YES 🗌 NO 📄 UNK CAN IT BE DRIVEN?								YES			UNK	
PHYSICAL APPEARANCE																		
BODY	FRONT P HEAD LIG HOOD TURN SIG GRILL L FRONT L REAR P SAFETY I REAR PA TAIL LIGH FRAME TURN SIG R FRONT R FRONT	SHTS SNALS PANEL PANEL LIGHTS NEL ITS SNALS PANEL					Missin Scratc Scratc	COMMENTS Missing Scratched Scratched Scratched					OPTIONS ENCLOSED CAB TINTED GLASS AIR CONDITIONER HEATER AIR RIDE SEAT AM FM RADIO TAPE DECK CD PLAYER BUCKET QUICK COUPLER HYD THUMB TRACK WIDTH ROP					
GLASS TIRES	R REAR PANEL WORK LIGHTS TOP L FRONT L REAR (S/D?) R FRONT R REAR (S/D?) TRACKS WINDSHIELD L DOOR REAR WINDOW R DOOR MIRRORS DASH/GUAGES							% % % %	SIZE: SIZE: SIZE: SIZE:									
INTERIOR	DOOR PANELS								IMENTS									
AL	ENGINE	IISSION		\boxtimes					ck engin		Low fu	iel.						
MECHANICAL	DIFFERENTIAL UNDERCARRIAGE BRAKES FRONT END REAR END																	
BATTERY/ELECTR Device A contract of the second device and second device and scraped throughout. Bucket has missing or broken teeth.																		

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107