	BC	Services In X TRUCK								RTR #: 4113038 ACCOUNT NUMBER: ACCOUNT NAME:					
CONDITION REPORT YEAR: 2018				MIL	MILES 343,502					VIN#: 1HTMMML9JH468557					
MAKE:		International		GV	<b>GVW:</b> 2		5,999 <b>BOX H</b>		8'	BOX LEN	BOX LENGTH 28'		BOX WIDTH 8'		
MODEL:		4300		WH	WHEELBASE:		272		COLOR:	EXTERIOR:	Yellow	INTE	RIOR:	Gray	
ENGINE:		Cummins ISB 6.7I		HP	HP			KE	EYS: IGNITION: 🛛 YES 🗌 NO 🔸 DOOR:		R: 🛛 YE				
TRANS: A		Automatic	Automatic		FUEL: 🗌 GAS		DIESE	L AN	NTIFREEZE TESTED: 🗌 YES 🖾 NO		RATI	RATING:			
	DOES M	OTOR RUN?	X YE	s [				N IT BE DRIVEN? 🛛 YES 🗌 NO COLLISION D/			AMAGE	MAGE? XES DO			
				_					_ APPEARA	ANCE					
BODY	FRONT BUMPER		GD	FR	PR	N/A		MENTS scratched					OPTIONS		
		HEAD LIGHTS		$\bowtie$			Bona	ooratoriou					BRAKES		
	HOOD TURN SIGNALS			$\boxtimes$			Crack	ed					⊠ AIR ∏ HYD		
	GRILL			$\boxtimes$										ĸs	
	D FRONT FENDER			$\boxtimes$									PWR WIND		
	D DOOR D BOX			$\boxtimes$			Scrap	od				-	PWR SEA		
		REAR BUMPER					Scrap	leu				$\square$	AIR COND		
		TAIL LIGHTS		$\bowtie$									AIR RIDE		
	REAR PANEL P FRONT FENDER											$\square$	AIR RIDE S		
	P FRONT DOOR			$\boxtimes$									TAPE / CD		
	P BOX			$\boxtimes$			Scrap	ed					SLEEPER		
TIRES	TOP D FRONT			$\boxtimes$			50 %	11R22.5 \$	SIZE:				E-TRACK	CENT ROOF	
	D REAR A1 (S/D?)							% 11R22.				BOX DOME LIGHT			
	D REAR A2 (S/D?) P FRONT			$\square$		$\square$	<b>50</b> %	%	SIZE:					R	
	P REAR A1 (S/D?)			$\boxtimes$				50 % 11R22.5 SIZE: 50/50 % 11R22.5 SIZE:					FUEL TANKS		
	P REAR A2 (S/D?)					$\boxtimes$		%	SIZE:				DUAL GAL		
	SPARE WINDSHIELD						Chip	%	SIZE:				MUD FLAF IEELS	°S	
LASS	D FRONT DOOR			$\boxtimes$			Chip							NUM	
	REAR WINDOW			$\boxtimes$											
G	P FRONT DOOR MIRRORS			$\boxtimes$			P/S b	roken w/ re	nair					:	
	DASH								s exposed.				EXHAUST		
Ř		DOOR PANELS SEAT(S) FLOORING		$\boxtimes$								SU	SPENSION		
RIOR	FLOOR												⊠ AIR □ SPRINC	G	
INTE	HEADL	HEADLINER		$\boxtimes$									🗌 PAD		
=	SLEEPER BOX			□ □ □ □ □ Chip on floor							日	TANDEM A ENGINE B			
	БОХ	GD	FR	PR		N/A	COMME	NTS:				TOOL BO	x		
MECHANICAL		ENGINE TRANSMISSION CLUTCH		$\boxtimes$				Oil leak					LIFT/TAG	AXLE	
				$\square$			$\square$	-				$\square$	RAMP LIFT GATE	=	
		DIFFERENTIALS		$\boxtimes$										-	
	BRAKES			$\boxtimes$											
	FRONT END REAR END			$\boxtimes$											
	BATTERY/ELECTR			$\boxtimes$											
REFRIGERATION Image: Commentation in the															
L							11	/18/2024							

1/18/202

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107