RTR Services Inc.										RTR #: 411307					7-01		
	AU	ITO				16					UMBER:						
С		N REPOR	T			I MAZANIA		10070100	A	CCOUN	T NAME:	=0	140				
YEAR: 2022 MAKE: Mercedes-Benz				VIN:		JG6EB5N	NG070108	ST:		TA	MILES:	12	.,878	YR:			
MAKE: Mercedes-Benz MODEL: AMG GLC43						TEDIOD	White	31:		NTERIOR:	Black/Re	\		IK:			
ENGINE: Mercedes 3.0L			COLOR: EXTERIOR: White INTERIOR: Black/Red KEYS: IGNITION: ⋈ YES □ NO • DOOR: ⋈ YES □ NO • TRUNK: ⋈ YES □ NO														
TRANS: Automatic				FUEL								YES NO RATING					
			NO					□ №	COLLISION DAMAGI			☐ YES	⊠ NO				
PHYSICAL APPEARANCE																	
	ED ONE D	GD FR		PR	N/A	COMMENTS						OPTIONS OPTIONS OPTIONS OPTIONS OPTIONS OPTIONS OPTIONS OPT					
	FRONT B											\boxtimes	PWR SI				
	HOOD			\boxtimes									\boxtimes	PWR LC	_		
	TURN SIGNALS														INDOWS		
													PWR SE	ER SEATS			
				\boxtimes									\boxtimes		IRRORS		
ВОДУ	D REAR DOOR D REAR FENDER			\boxtimes										CRUISE TILT W	CONTROL		
BO	REAR BUMPER		╁╏		╁╬									TINTED			
															NDITIONER		
	TRUNK TAIL PIPE			\boxtimes										SUN RO	_		
	P FRONT FENDER			\boxtimes										TAPE D	ECK		
	P FRONT DOOR P REAR DOOR			\boxtimes									\boxtimes	CD PLA	YER M WHEELS		
	P REAR FENDER													AWD	WI WITELS		
	TOP			\boxtimes										_	ACKAGE		
TIRES				$\boxtimes \boxtimes$				255/40 ZR2 255/40 ZR2					\square	NAVIGA	ATION		
	P FRONT			\boxtimes			90 % 2	285/35 ZR2	1 SIZE:								
F	P REAR SPARE						90 % 2	285/35 ZR2 %	1 SIZE:								
GLASS	WINDSHIELD				\Box			70	DIZE.								
	D FRONT DOOR			\boxtimes													
	D REAR DOOR P FRONT DOOR			\boxtimes													
9	P REAR D			\boxtimes													
REAR WI		NDOW			$\frac{ }{ }$												
O.R.	DOOR PA	NELS		\boxtimes													
INTERIO	SEAT(S)			\boxtimes													
Z	CARPET HEADLIN	ER	\parallel	\boxtimes													
	•		GD	FR	PR	UKN	N/A	COMME				_					
٦	ENGINE TRANSMI	ISSION		\boxtimes				Service I	ight on. S	uspected	cause to be	overdue c	il ch	ange nee	eded.		
MECHANICAL	CLUTCH	BRAKES					\boxtimes										
HA																	
Ē	FRONT END REAR END			\boxtimes	1 🖁		ll										
	BATTERY			\boxtimes													
СО	MMENTS:	Mileage unv	erified.	Dash	displa	ys overd	lue servi	ce note, ne	eds oil ch	nange.							
							11/1	2/24							_		
	EM	PLOYEE'S FULL By sig				ertify all infor	mation cont	DATE tained within thi	s report to be	true and accu	EMP rate to the best of	LOYEE'S SIG f my knowledg					