RTR Services Inc.								RTR #: 4113773												
BOX TRUCK					410			ACCOUNT NUMBER:												
	CONDI	TION REPO	RT		-0			ACCOUNT NAME:												
YEAR: 2012			MIL	.ES	Unkno	VIN # : 5PVNE8JV5D4S52647														
MAKE: Hino			GV	GVW: 25		BOX	HEIGHT	ВОХ			X LENG	ENGTH 26.8			BOX WIDTH					
MODEL: 268				WH	IEELB	ASE:		_			COLOR: EXTERIOR: White				INTERIOR: White, Wo					
ENGINE: J08E-VC/VB			В	HP					EYS: IGNITION: 🛛 YES 🗌 NO • DOOR					R: 🛛 Y	. ⊠ YES □ NO					
TRANS: Automatic				FUEL: GAS			DIESEL	ITIFRE	TIFREEZE TESTED: ☐ YES ⊠ NO				RAT	RATING: Unknown						
DOES MOTOR RUN?				/ES	ES ⊠ NO COLLISION DAMAGE? ⊠ YES □ NO													·		
PHYSICAL APPEARANCE																				
		GD	FR	PR	N/A		OMMENTS								_	OPTIONS				
ВОДУ	_	BUMPER								nor Scratches							PWR STEERING AKES			
	HEADLIGHTS HOOD TURN SIGNALS GRILLE								Driver And Passenger Side							KA				
							Denter With Minor Scratches							│ │ │ │ │ │ │						
		NT FENDER		\boxtimes												_	3			
	D D00							Step Is Misssing												
	D BOX	BUMPER						Dented												
	TAILLI	_					Liftgate	Has D	ents A	nts And Scratches						_	AIR RIDE SEAT D/P			
	REAR															_	AIR RIDE SUSPENSION AM FM RADIO			
		NT FENDER			\boxtimes		Cracked	d And S	cratch	nes						_				
	P FRONT DOOR														—		CD / CB? SLEEPER SIZE?			
	P BOX TOP			\boxtimes														ER SIZE LUCENT		
TIRES	D FROI			\boxtimes			%	SIZE:							\triangleright	₫		K LININ		
	D REAR A1 (S/D?) D REAR A2 (S/D?)						%	SIZE:							[2		BOX DO	OME LIG	HT	
	P FRONT			\square			%	SIZE:									L TANK			
	P REAL		\boxtimes			%	SIZE:									SINGLE GAL 90_				
	P REAL				\boxtimes	%	SIZE:										L GAL _			
	SPARE					%	SIZE:							│						
SS	D FRONT DOOR																	MINUM		
GLAS	REAR WINDOW						Scratch	es									STE			
G	P FROM	NT DOOR		\boxtimes													☐ BUD☐ SPO			
~	DASH	N.S					Missing	Parts												
		PANELS		\boxtimes										s	SUSPENSION					
INTERIOR	SEAT(S)																	INIC		
臣	FLOORING HEADLINER						Black N	Narke												
Z	SLEEPER						DIACK IV	LUINS								_		M AXLE		
	вох															_	Ξ			
	ENGIN		GD 🗆	FR	PR	UKN		COMME								_	TOOL E			
MECHANICAL		ENGINE TRANSMISSION						Keporte	d To l	Have	A Bl	own En	ıgiı	ne			LIFI/IA RAMP	G AXLE	:	
	CLUTC					\boxtimes											LIFTGA	TE		
		RENTIALS				\boxtimes		Body D	amage	е То	Front						CAMER	A SYST	EM	
	BRAKE	-													□					
	FRONT REAR I														 					
	BATTE						Batteries Are Dead													
		GERATION							ON ONLY / DEF & DPF FUNCTIONS N				OTIONO NO]	DIN'-	D DES-	ONCIDI T		
то	VALIDA [*]	TE / WE RECO	MMEND	YOL	JINSF	ECT PR	IOR TO PL	JRCHAS	Ē											
COMMENTS: Mileage Unverified. Oil Pan Is Missing Bolts And Has A Hole In It, The #6 Rod Was Thrown Leaving Metal Shavings In The Engine																				
	-	EMPLOYEE'S FUL						/2025 DATE	and sa		tho ba-	t of my limit	wile d	EMPLOYEE			E			