RTR Services Inc. RTR #: 4113828-01																	
RTR Services Inc. BOX TRUCK					all				RTR #: 4113826 ACCOUNT NUMBER:				20-01	0-01			
CONDITION REPORT					(C					ACCOUNT NAME:							
<b>YEAR</b> : 20		2018		MIL	.ES	203,298			VIN#:	1HTMMMM	LXJH44671	14					
MAKE:		International		GV	W:		ВО	K HEIGHT	12'0"	BOX LEN	IGTH 26'	'	BOX V	VIDTH	102	ıı	
MODEL:		4300 SBA		WH	IEELE	BASE:			COLOR: EXTERIOR: Yellow			INTERIOR: Gray					
ENGINE:		Cummins 6.7L			HP			KI	KEYS: IGNITION: 🛛 YES 🗌 NO • DOOR: 🖸			YES	☑ YES □ NO				
	RANS:	Automatic	1			☐ GAS ⊠ DIESEL			NTIFREEZE				RATIN	_			
DOES MOTOR RUN?   X YES   NO   CAN IT BE DRIVEN?   X YES   NO   COLLISION DAMAGE										IAGE?	⊠ Yi	ES	□ NO				
			GD	FR	PR	N/A							OPTIONS				
ВОДУ	FRONT BUMPER					IN/A		Driver side bent									
	HEAD LIGHTS HOOD TURN SIGNALS GRILL D FRONT FENDER D DOOR D BOX						Dama						BRA	AKES			
						Damaged, unable to open								⊠ AIR □ HYD			
							Detacl	ned, in bo	ОХ				$\dashv$	PWR L		S	
					□ □ Damaged									ows			
				$\boxtimes$										PWR S			
	REAR BUMPER			$\boxtimes$		<del>                                     </del>							$\exists \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$			IONER	
	TAIL LIGHTS															EAT D/P	
	REAR PANEL P FRONT FENDER			$\boxtimes$									$\dashv \boxtimes$	AIR RI		JSPENSION IO	
	P FRONT DOOR			$\boxtimes$										TAPE /			
	P BOX TOP			$\boxtimes$									-   무	SLEEP			
TIRES	D FRONT			$\boxtimes$	-		85 %	11R22.5	SIZE:				$\exists \exists$	E-TRA		ENT ROOF NING	
	D REAR A1 (S/D?)			$\boxtimes$				11R22.5	SIZE:					BOX D	OME	LIGHT	
	D REAR A2 (S/D?) P FRONT						QE 9/	<u>%</u> 11R22.5	SIZE:				┦ 🖺 📙	SIDE D			
	P REAR A1 (S/D?)							11R22.5					- 100			GAL	
	P REAR A2 (S/D?)					$\boxtimes$		%	SIZE:				]_	☐ DU	AL GA	AL	
	SPARE WINDSHIELD						Driver	% side cra	SIZE:					MUD F EELS	LAPS	<b>i</b>	
SS	D FRONT DOOR REAR WINDOW P FRONT DOOR MIRRORS			$\boxtimes$												JM	
LAS				$\boxtimes$										⊠ STEEL ⊠ BUD			
0			ᅵᅢᅦ		ΙH	1											
ERIOR	DASH DOOR PANELS SEAT(S) FLOORING HEADLINER SLEEPER BOX			$\boxtimes$										EXHAL	JST S	/D?	
														SPENSION IN THE SERVICE SERVIC			
														⊠ SPF	RING		
INTERI				$\boxtimes$									]_	☐ PAI			
_													ᅥ붐				
			GD	FR	PR	UKN	N/A	COMME						TOOL	вох		
MECHANICAL	ENGIN			$\boxtimes$				Warning	g Engine Err	or				LIFT/T	AG A	XLE	
	TRANSMISSION CLUTCH													LIFT G	ATE		
	DIFFERENTIALS			$\boxtimes$										Heater			
	BRAKES		ᅵ片ㅣ	$\boxtimes$													
Ħ	FRONT END												┨╏				
	BATTERY/ELECTR			$\boxtimes$								]					
CO		SERATION S: Mileage un	verified.	Colli	son d	⊥ ⊔ lamage to	driver :	side.									
		<b>J</b>				<b>J</b> = 1-											
							1/9	9/25									
	-	EMPLOYEE'S FUL By si					ormation co	DATE ontained with	in this report to be	e true and accura		PLOYEE'S S					