	RTR	Services In								RTR #: 411387						8-04			
TRAILER											ACCOUNT NUMBER:								
CONDITION REPORT YEAR: 2015				BODY	TYPE:	Dry Van			ACCOUNT NA				31554						
MAKE: Hyundai				LICENSE:		Dry van		STATE:		3113 ¥ 332 €		TAGS: MN:				YR:			
MODEL: VC2530152A		JS		COLOR:		EXTERIOR: W		w	hite		I		INTERIOR:		White/Brown/Aluminum				
LENGTH: 53				WIDTH:					HEIGHT:						GVW : 68000				
HITCH: GOOSE		☐ GOOSE N	ECK	□Р	PINTLE 🛛 5 TH		WHEEL PIN 17			7/8" BALL		 □ 2" BALL		☐ 2 5/16" BA		ALL			
IS IT ROAD READY? ☐ YES					⊠ NO		COLLISION DAMA			AGE? ☐ YES ☐ N		⊠ NC)	KEYS:		☐ YES	⊠ NO		
PHYSICAL APPEARANCE																			
			GD	FR	PR	N/A	COMI	MENTS										TIONS	
TIRES INTERIOR BODY	REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A2 (S/D?)						% 10 % % % 10 % 10	SIZE: SIZE: 25/ SIZE: 25/ SIZE: SIZE: SIZE: 25/ SIZE: 25/	75/R 75/R 75/R 75/R	22.5	2.5						SPRING SUSPENSION AIR BRAKES ELECTRICAL BRAKES HYD BRAKES SLIDER AXLE WHEELS BUD SPOKE STEEL ALUMINUM LIFT/TAG AXLE SPARE TIRE RACK REFIGERATION UNIT REEFER HRS TOOL BOX MUD FLAPS ROLL UP REAR DOOR LOADING RAMP BATTERY		
							% SIZE: □ % SIZE: □												
MECHANICAL	CLEAR SLIDEF REFRIC LANDII AIR HO ELECT	L LIGHTS ANCE LGT R AXLES GERATION NG GEAR PSE/GLAD R PIGTAIL	GD	FR	PR		N/A	COMM	ENT	S:									
COMMENTS: Scratched and Dented Throughout.																			
12/04/2024																			
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.																			