


**RTR Services Inc.  
PICK-UP TRUCK  
CONDITION REPORT**



**RTR #:** 4121045  
**ACCOUNT NUMBER:**  
**ACCOUNT NAME:**

YEAR:	2015	VIN:	3FRWX6FC1FV525145			MILES:	34867		
MAKE:	Ford	LICENSE:		STATE:		TAGS: MN:		YR:	
MODEL:	F650	CAB TYPE:	Extended	COLOR:	EXTERIOR: White	INTERIOR:	Gray		
ENGINE:	6.7L	KEYS: IGNITION: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO • DOOR: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO							
TRANS:	6 Speed	FUEL:	<input type="checkbox"/> GAS <input checked="" type="checkbox"/> DIESEL <input type="checkbox"/> HYBRID	ANTIFREEZE TESTED:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	RATING			
DOES MOTOR RUN?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	CAN IT BE DRIVEN?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	COLLISION DAMAGE?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				

**PHYSICAL APPEARANCE**

	GD	FR	PR	N/A	COMMENTS	OPTIONS
BODY	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR STEERING
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR BRAKES
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> PWR LOCKS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR WINDOWS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR SEATS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	paint is chipped	<input checked="" type="checkbox"/> LEATHER SEATS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> PWR MIRRORS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> CRUISE CONTROL
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> TILT WHEEL
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> TINTED GLASS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AIR CONDITIONER
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> CUSTOM WHEELS
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/> SUN ROOF
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		<input checked="" type="checkbox"/> AM FM RADIO
TIRES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	90 % 245/70/R19.5 SIZE:	<input type="checkbox"/> 4 X 4
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	90 % 245/70/R19.5 SIZE:	<input type="checkbox"/> TOW PACKAGE
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	90 % 245/70/R19.5 SIZE:	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	90 % 245/70/R19.5 SIZE:	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	% SIZE:	
GLASS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
INTERIOR	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	scratches/ dings/ dirty	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	ripped fabric / scratches	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
MECHANICAL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		

**COMMENTS:** Mileage Unverified. Passenger side steps have some dings and are scuffed up. The storage box and cabinets have some chipped paint and dings/ dents inside and out. The inside of the storage cabinets have been sprayed with color paint and looks a little dirty. Driver side storage cabinets and box also have some chipped paint and scratches/ dents. They look a little dirty. The driver side doors have some chipped paint. Inside of cab has some scratches and the plastic is ripped on the V-TEC.

1/1/2025

**EMPLOYEE'S FULL NAME (PLEASE PRINT)**

**DATE**

**EMPLOYEE'S SIGNATURE**

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

---

---

**RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421**

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

---