

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #: 4121267-01
				ACCOUNT
				ACCOUNT NAME:
YEAR:	2024			
MAKE:	AST	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	200-1G	<input checked="" type="checkbox"/> OPERATIONAL		
SN:	4M9B41111RD17741	<input type="checkbox"/> NON OPERATIONAL		
POWER:	Kohler 20.5 Hp	<input type="checkbox"/> UNTESTABLE		
DESCRIPTION:	2024 AST-200-1G Drywall Texture Sprayer Rig, S/A Trailer Mounted, Vin: 4M9B41111RD177412			
SHOT / COUNT / HOUR: Hour Meter Reads: 1.28 (Unverified),				
NOTES / COMMENTS: 2" Ball Hitch; Length: 11ft; Width: 6ft; Height: 4ft				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:
				ACCOUNT
				ACCOUNT NAME:
YEAR:				
MAKE:		<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		<input type="checkbox"/> OPERATIONAL		
SN:		<input type="checkbox"/> NON OPERATIONAL		
POWER:		<input type="checkbox"/> UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:
				ACCOUNT
				ACCOUNT NAME:
YEAR:				
MAKE:		<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		<input type="checkbox"/> OPERATIONAL		
SN:		<input type="checkbox"/> NON OPERATIONAL		
POWER:		<input type="checkbox"/> UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				

12/26/24

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107