RTR Services Inc. EXCAVATOR WHEEL/TRACK CONDITION REPORT				VIN/SN: A35578				RTR #: 412224 ACCOUNT NUMBER: ACCOUNT NAME:					4-01					
YEAR: 2017				VIN/S														
MAKE: Komatsu				□ WHEEL ☑ TRACK COLOR: EXTERIOR: Yellow INTERIOR: Bla														
MODEL: PC360LC-11 ENGINE: Komatsu Diesel			COLO					1/4				lack						
TRANS: Hydraulic											TED: 🗌 YE			TING:				
HRS: 5,948														YES) 🗆 UN		
	TINO:	3,740			DUES			YSICAL							IES			IN I
			GD	FR	PR	N/A		COMMENTS					OPTIONS					
BODY	FRONT PANEL HEAD LIGHTS HOOD TURN SIGNALS GRILL L FRONT PANEL L REAR PANEL SAFETY LIGHTS REAR PANEL TAIL LIGHTS FRAME TURN SIGNALS R FRONT PANEL R FRONT DOOR R REAR PANEL							Paint scraped off						ENCLOSED CAB TINTED GLASS AIR CONDITIONER HEATER AIR RIDE SEAT AM FM RADIO TAPE DECK CD PLAYER BUCKET QUICK COUPLER HYD THUMB TRACK WIDTH <u>16'</u> ROP				
GLASS TIRES	WORK LIGHTS						40%	% % %	SIZE SIZE SIZE SIZE	:								
INTERIOR	DOOR PANELS SEAT CARPET/MAT CONTROLS						Mat flo											
	ENGINE		GD	FR	PR		N/A	COMN	IENTS:									
L TRANSM DIFFERE UNDERC H BRAKES D FRONT E W REAR EN		MISSION ENTIAL CARRIAGE S END																
CO		Hours unver	ified				1/8/2	25										

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107