RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	4123147-01
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2012				
MAKE:	Vermeer	☒ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	D9X1311	☒ OPERATIONAL			
SN:	0097	☐ NON OPERATIONAL			
POWER:	Diesel	☐ UNTESTABLE			
DESCRIPTION:	2012 Vermeer D9X13 Series II Directional Drill				
SHOT / COUNT / HOUR: 4,761					
NOTES / COMMENTS: Hours unverified. S/N: 1VR9160S3C1000484					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:					
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:		☐ OPERATIONAL			
SN:		☐ NON OPERATIONAL			
POWER:		☐ UNTESTABLE			
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:					
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:		☐ OPERATIONAL			
SN:		☐ NON OPERATIONAL			
POWER:		☐ UNTESTABLE			
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

1-7-2025

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107