RTR Services Inc. BOX TRUCK									RTR #: 412315 ⁴ ACCOUNT NUMBER:					51-01	1-01				
CONDITION REPORT				6				ACCOUNT NAME:											
YEAR: 2022		2022		MIL	MILES 87		548		VIN#:	VIN#: 1FC3E3KN		6NDC23930							
MAKE:		Ford	Ford Ford		GVW : 11500			X HEIGHT	•		BOX LEN	GTH 1	2'	вох	WIDTH				
MODEL:		E350		WH	WHEELBASE:				COLOR: EXTERIOR: White				INTERIOR: Black						
EI	NGINE:	V8 7.3L		HP					KEYS: IGNITION: YES NO • DOOR: Output Description:					☐ YE] YES ⊠ NO				
TRANS: Automatic						GAS 🗌		l l	NTIFREEZE TESTED: YES NO				RATING: -20						
DOES MOTOR RUN? YES NO CAN IT BE DRIVEN? YES NO COLLISION DAMAGE? YES												ES	⊠ NO						
			GD	FR	PR	N/A		MENTS	L APPEAK	AIN	J E					OPTIC	NS		
ВОДУ	FRONT	BUMPER		\boxtimes			COMIN	COMMENTO											
	HEAD LIGHTS HOOD TURN SIGNALS													BR	_ BRAKES □ AIR				
				\boxtimes											□ AIK ⊠ HYD				
	GRILL DEPONT FENDER			\boxtimes										$\exists \sqsubseteq$					
	D FRONT FENDER D DOOR			\boxtimes										┨╏	PWR W				
	D BOX				\boxtimes		Dents	and Scra	tches						PWR N	IIRRO	RS		
	REAR BUMPER TAIL LIGHTS			\boxtimes										$-\mid \boxtimes $	AIR CC		IONER :AT D/P		
	REAR PANEL			\boxtimes											AIR RII		SPENSIC	ON	
	P FRONT FENDER P FRONT DOOR						Won't	open or o	Noso										
	P BOX			\boxtimes			WOIIL	open or c	,105 6 .					ᅥᆸ					
	TOP	\IT				 	25 0/	25 % 225/75R16 SIZE:							☐ TRANSLUCENT ROOF☐ E-TRACK LINING			F	
TIRES	D FRONT D REAR A1 (S/D?)								6 SIZE: 5R16 SIZE:	:				$\dashv \square$					
	D REAR A2 (S/D?)					\boxtimes	% SIZE: 10 % 225/75R16 SIZE:							SIDE DOOR					
	P FRONT P REAR A1 (S/D?)				\boxtimes			225/75R10 225/75R10						- FU	EL TANK SIN		BAL		
	P REAR A2 (S/D?)					\boxtimes	% SIZE:							☐ SINGLE GAL ☐ DUAL GAL					
	SPARE WINDSHIELD						% SIZE: pasenger side cracked						☐ MUD FLAPS WHEELS ☐ ALUMINUM						
3LASS	D FRONT DOOR REAR WINDOW P FRONT DOOR MIRRORS			\boxtimes			pasenger side cracked					┨ ```							
							front side window cracked						☐ STEEL ☐ BUD						
				\boxtimes										-		KE			
	DASH DOOR PANELS SEAT(S) FLOORING HEADLINER														EXHAU SPENSIC		/D?	_	
IOR												╛	☐ AIR						
INTERI				\boxtimes											⊠ SPF				
Z	SLEEPER													\dashv \Box	TANDE		LE		
	вох						scrato		NITO.						ENGIN		AKE		
AL	ENGIN	E	GD	FR ⊠	PR	UKN	N/A	engine a	and ABS lig	ghts	are on.				TOOL I		(LE		
		MISSION		\boxtimes]			_						\Box	RAMP				
SI	CLUTCH DIFFERENTIALS						\square								LIFT G Shelvir				
MECHANICAL	BRAKES			\boxtimes										\boxtimes	Rolling	j Door			
	FRONT END REAR END														Heater				
	BATTERY/ELECTR			\boxtimes										╛					
CO		GERATION S: Miliage Unv	erified	Minor	r Dam	lage And	Scuffs	On Exteri	or and Inte	rior	No Keve	To Slide	Door						
COMMENTS: Miliage Unverified. Minor Damage And Scuffs On Exterior and Interior, No Keys To Slide Door																			
1/27/2025																			
		EMPLOYEE'S FUL By si					ormation co	DATE ontained within	n this report to I	be tru	ue and accura		IPLOYEE'S t of my knowl						