RTR Services Inc.										RTR #: 4123376-02										
BOX TRUCK										ACC										
CONDITION REPORT					1					A	CCOUN	T NAM	3							
YEAR: 2022				MIL	LES	Unknow	nown			VIN#: 1FC3E3KN0NDC23907										
MAKE: Ford			GVW:		11500		X HEIGH	Г		BOX LE	NGTH	12'	E	BOX W	/IDTH					
MODEL: E350		E350		WH	HEELE	BASE:			С	OLOR: E	EXTERIOR: White		ı	INTERIOR:			ck			
ENGINE: 7.3L		7.3L	HP					K	KEYS: IGNITION: ⊠ YES □ NO • DOOR:					OR: [	☐ YES ⊠ NO					
TRANS: Automatic			FUEL: [		☐ GAS ☐	DIESE	L A	NTIFREEZE TESTED: ⊠ YES □ NO				ı	RATING: -20							
DOES MOTOR RUN?		☐ YE	S 🛮 🖾 NC		CA	AN IT B	E DRIVEN	1?	☐ YES	⊠ NO	COL	LISION	I DAM	AGE?	☐ YE	S 🗵	] NO			
								PHYSICA	AL A	APPEARA	NCE									
ВОДУ		GD	FR	PR	N/A	COM	MENTS						OPTIONS							
		BUMPER		$\boxtimes$										☐ ☑ PWR STEERING BRAKES						
	HOOD	Lioiiio					passe	enger side	e hinge is broken				☐ AIR							
	TURN SIGNALS			$\boxtimes$									HYD							
	GRILL D FRONT FENDER						Camera knocked off							<ul><li>□ PWR LOCKS</li><li>□ PWR WINDOWS</li></ul>						
	D DOO										PWR SEATS									
	D BOX			$\boxtimes$													☐ PWR MIRRORS			
	REAR I	BUMPER		$\boxtimes$	⊠ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □															
	REAR			$\Box$	_   _												1			
		NT FENDER		$\boxtimes$													<b>RADIO</b>	)		
	P FRONT DOOR P BOX			$\boxtimes$												TAPE /			_	
	TOP			$\boxtimes$	$\parallel$	1									☐ SLEEPER SIZE? ☐ TRANSLUCENT ROOF					
TIRES	D FRO							225/75R1							E-TRACK LINING					
	D REAR A1 (S/D?) D REAR A2 (S/D?) P FRONT P REAR A1 (S/D?)						25 % 225/75R16 SIZE: % SIZE:													
							25 % 225/75R16 SIZE:													
				$\boxtimes$				225/75R1	6 5						☐ SINGLE GAL ☐ DUAL GAL ☐ DUAL GAL ☐ MUD FLAPS					
		R A2 (S/D?)						% SIZE:												
	SPARE WINDSHIELD							% mudflaps are torn SIZE:								MUD FI EELS	LAP5			
GLASS		NT DOOR										<b>⊠</b> ALUMINUM								
		WINDOW					amall window is avealed				☐ STEEL									
19	MIRRO	NT DOOR RS						small window is cracked driver mirror cracked and particles of the cracked			part	□ BUD □ SPOKE								
							is mis	ssing.						<b>J</b>						
	DASH	DANELS					The column, start button and shifter are missing.  scratches throughout.				SUSPENSION									
OR	SEAT(S	PANELS S)		$\boxtimes$						ughout.				303						
INTERIO	FLOOR	RING		$\boxtimes$											☐ AIR					
Ī	HEADL SLEEP														۱_	☐ PAD		_		
	BOX	EK	ΙHΙ	H										┨	ENGIN					
			GD	FR	PR	UKN	N/A	COMM	ENT	NTS:				TOOL BOX						
MECHANICAL	ENGIN	SMISSION						Won't s	tart	t, the cool	ant lid is	missing.			+B	LIFT/TA	AG AXL	.E		
	CLUTC														1 🗂	LIFT G	ATE			
		RENTIALS				$\boxtimes$														
	BRAKE FRONT	-																		
	REAR						H						] 🗇							
~	BATTE									take a jur	np start, l	oox said	short		1 🗖					
	RFFRIG	GERATION						circuit.	uit.				$\dashv_{\sqcap}$							
СО		B: Miliage Unv	erified.		<u>,                                    </u>		, <u>—</u>								<u>,                                    </u>					
							1/	27/2025												

