RTR Services Inc. HEAVY TRUCK										RTR #:  4123742    ACCOUNT NUMBER:								
CONDITION REPORT							91		ACCOUNT NAME:									
YEAR: 2020			_	MILES 482,78		-	LICENSE:		VIN#:	1XKYDP9X	XLJ36062	-	Non				[	
MAKE: Kenworth				GVW: 52K WHEELBASE:			NSE:			ST:				MONTH YR:				
MODEL: T680			HP		-	234						INTERIOR:        Gray          □ NO • DOOR: □ YES □ NO						
ENGINE:        Paccar MX-13 12.9L          TRANS:        10 Speed Manual				-		-												
DOES MOTOR RUN?			_	FUEL: 🗌 GAS 🖂														
	0020									APPEARAN		0022						
	GD			FR	PR	N/A	COM	COMMENTS								OPTIONS		
ВОДУ	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS				$\boxtimes$									PWR STEERING				
				$\square$			Supp	ort stru	ictu	ire missing,	hood twist	ed.		BR	AKES 🖂 AI	R		
				$\boxtimes$											🗌 Н`	YD		
	GRILL D FRONT FENDER														PWR			
	D DOOR			$\square$	$\square \boxtimes$									$\square$	PWR			
	D SLEE													PWR	MIR	RORS		
	REAR																	
	TAIL LIGHTS REAR PANEL			$\boxtimes$										$\square$			SEAT SUSPE	ENSION
	P FRONT FENDER			$\boxtimes$										$\square$	CON	V. 5 <sup>⊤</sup>	<sup>H</sup> WHEI	EL
	P FRONT DOOR P SLEEPER			$\boxtimes$											SLID AM F	-	5 <sup>™</sup> WH	EEL
	TOP			$\boxtimes$			-							$\square$			D/CB?	,
TIRES	D FRONT				$\square$					.5 SIZE:					SLEE	PER	SIZE?	
	D REAR A1 (S/D?) D REAR A2 (S/D?)			$\boxtimes$						.5 SIZE:								GTAIL
	P FRONT				$\square$			50 % 295/70/22.5 SIZE: 20 % 295/70/22.5 SIZE:							GLAD HANDS			
	P REAR A1 (S/D?)			$\boxtimes$				50 % 295/70/22.5 SIZE:							SINGLE GAL			
	P REAR A2 (S/D?) SPARE						50 %	<u>295/70 %</u>	)/22	.5 SIZE: SIZE:							GAL <u>12</u> PS	<u>20_</u>
	WINDSHIELD						Crack			512L.					EELS		15	
SS	D FRONT DOOR			$\boxtimes$														
GLAS:	REAR WINDOW P FRONT DOOR					$\square$									⊠ S1 ∏ BI		-	
0	MIRRORS				$\boxtimes$		D/S N	lirror d	ama	aged					🗌 SF	РОК		
~	DASH		$\square$													Г <b>S/D</b> ?	<u>s_</u>	
ERIOR	DOOR PANELS SEAT(S)			$\boxtimes$								SU	SPENS					
	CARPET			$\boxtimes$													G	
INT	HEADLINER SLEEPER			$\bowtie$											🗌 Р/	٩D		
	SLEEP	GD	FR	PR		N/A	COM	IME	NTS:							AXLE BRAKE		
MECHANICAL	ENGIN						Fuel	cap	os missing, f	uel lines di	isconnec	ted, and		TOO				
	TDANG	MISSION						wires	s cı	ıt.				$\neg$		тлс	AXLE	
	TRANSMISSION CLUTCH					$\boxtimes$									WET		AALE	
	DIFFERENTIALS					$\square$												
	BRAKES FRONT END					$\boxtimes$												
	REAR END																	
		RY/ELECTR							40-	will not an								
COMMENTS: Miliage Unverfied. The dash recieves power, but starter will not engage.																		
	12/26/24																	
	Τ	EMPLOYEE'S FULL By sig					nformation o	DA contained		n this report to be	true and accura		MPLOYEE'S					

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107