RTR Services Inc. HEAVY TRUCK										RTR #: 4123765 ACCOUNT NUMBER:									
CONDITION REPORT									ACCOUNT NAME:										
<b>YEAR:</b> 2013			MILES		491,229			VIN #: 3		HSDJSJR6DN157978						1			
MAKE: Internationa		International		-	<b>GVW:</b> 523		LICENSE:				ST:		TAGS:	MON	ТН	YR:			
MODEL: Prostar 122				WHEELBASE:				COLOR:		-	Whit		INTE	-	Gray				
ENGINE: Navistar MaxxF			HP			ODY TYPE:	-	eper											
TRANS: 10 Speed Manual					1						RATI	RATING:							
DOES MOTOR RUN? 🛛 YES 🔲 NO COLLISION DAMAGE? 🖾 YES 🗍 NO PHYSICAL APPEARANCE																			
			GD	FR	PR	N/A									OPTIONS				
	FRONT BUMPER						Damaged							PWR STEERING					
	HEAD LIGHTS HOOD			$\boxtimes$			<u> </u>						BR						
	TURN SIGNALS														☐ AIR ☐ HYD				
	GRILLE														PWR L		_		
≿	D FRONT FENDER D DOOR			$\boxtimes$										$\square \boxtimes$	PWRV		5		
вору	D SLEE	PER		$\square$											] PWR MIRRORS				
	REAR BUMPER		$\boxtimes$											AIR CONDITIONER					
														ㅓ님			PENSION		
	P FRONT FENDER			$\boxtimes$		Damaged													
	P FRONT DOOR		$\boxtimes$											SLIDING 5 <sup>TH</sup> WHEEL ▲ AM FM RADIO					
	ТОР [														TAPE / CD / CB? CD				
	D FRONT D REAR A1 (S/D?)				$\mathbb{Z}$		16 % 11R2												
ŝ	D REAR A2 (S/D?)						21 % 11R22.5 SIZE: 22 % 11R22.5 SIZE:								GLAD HANDS				
TIRES							19 % 11R22.5 SIZE:							FU					
	P REAR A1 (S/D?)						25 % 11R22.5 SIZE: 24 % 11R22.5 SIZE:							_	SINGLE GAL UUAL GAL				
	SPARE				□ □ 12 % 11R22.5 SIZE:									MUD FLAPS					
の D FRO		HIELD NT DOOR		$\boxtimes$										WH		JMINUM			
GLAS		WINDOW		$\square$															
		NT DOOR					D/C Broken	P/S Brokon Mirror Missing								□ BUD □ SPOKE			
MIRRC DASH		ĸJ		□         □         P/S Broken-Mirror Missing           □         □         □									$\neg$		JST S/D?	•			
R		PANELS		$\boxtimes$															
DOOR OSEAT( E CARPE				$\boxtimes$								_	AIR □ SPRING						
	SLEEPER			$\square$											TANDE	EM AXLE			
_	ENGINE		GD	FR				VIVE	NTS:						ENGIN TOOL	E BRAKI BOX	=		
MECHANICAL	TRANSMISSION			$\square$											LIFT/T	AG AXLE	E .		
	CLUTCH DIFFERENTIALS			$\boxtimes$											WET K	IT			
CH	BRAKE																		
Ψ	FRONT END																		
		END RY/ELECTR					Rep	lace	d 3/2025					$\exists$					
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																			
		SLE TO VALID					JU INSPECT		RICPUR	CHAS	<b>5C</b>								
		-																	
12/31/2025																			
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE																			
			All informa	ation cor	ntained v	vithin this re	port is deemed to b	e true	and accurate	to the be	est of my kr	nowledge a	as of the date lis	sted above	э.				

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125