RTR Services Inc.					RTR #: 5011476											5-01		
TRAILER CONDITION REPORT										ACCOUNT NUMBER: ACCOUNT NAME:								
YEAR: 2023			<b>71</b>		BODY	TYPE:	Dry V	an		VIN #: 3H3V532K4PJ114182								
MAKE:		Hyundai					_											
MODEL:		VC2530152-AJS			COLOR:			TERIOR:	White	White			TERIOR:	White				
LENGTH:		53'			WIDTH:		102"		HEIGHT: 13'6"		13'6"				<b>GVW</b> : 68,000			
HITCH:		☐ GOOSE NECK		□ PI	☐ PINTLE ☑ 5 <sup>TH</sup>		WHEEL PIN		1 7/8" BALL		L $\sqcap$	2 5/16" B	ALL					
CAN IT BE TOWED?			⊠ YE	S 🗆 NO				ON DAMA	GE?	? DYES NO			KEYS	3:	: Service : :			
								PHYSICAL APPEARANCE								<u>_</u>		
			GD	FR	PR	N/A	COM	MENTS								ONS		
ВОДУ	FRONT PANEL HITCH D SIDE PANEL SIDE DOOR (S)			$\boxtimes$											AIR F	RIDE	SUSPENSION	
				$\boxtimes$									$\perp \square$	│				
													_					
	REAR PANEL			$\boxtimes$											HYD		-	
	REAR DOOR (S) P SIDE PANEL			$\boxtimes$	$\parallel$									∣⊠ wн	SLIDI EELS	EK A	XLE	
	REAR I		$\boxtimes$	□ □ D Side dent								□BUD						
	TOP [			$\boxtimes$										-	☐ SI			
R	D SIDE			$\parallel$									-					
ERIOR	FRONT PANEL			$\boxtimes$						☐ LIFT/TAG AXLE								
N	P SIDE PANEL CARGO RAILS			$\boxtimes$											SPARE TIRE RACK HUB METER			
	CEILING														REEF	FER H	IRS	
TIRES	D REAR A1 (S/D?) D REAR A2 (S/D?)				$\boxtimes$			% 10 SIZE: 295/75R22.5 □ TOOL								DL BOX D FLAPS		
	D REAR A3 (S/D?)														OLL UP REAR DOOR			
							% 10 SIZE: 295/75R22.5											
-							% 10 SIZE: 295/75R22.5 % SIZE:							1	☐ LIFTGATE ☐ LOADING RAMP			
	SPARE					$\boxtimes$	% SIZE:							TRANSLUCENT ROOF				
ECHANICAL			GD 🗆	FR ⊠	PR	UKN	N/A	COMMI	ENTS:					18		_	LIGHTING RAMP	
	SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION			$\boxtimes$											BULL	_		
				$\boxtimes$										$\perp$	E-TR	ACK	LINING	
HZ																		
≥ LAND		NG GEAR		$\boxtimes$														
	AIR HOSE/GLAD ELECTR PIGTAIL																	
	S IS NO	T A MECHANIC	CAL INS	PEC								JNITS: I	EMISSION	S NO	T VERI	IFIED	, BUYER	
RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE  COMMENTS: Wires banging from bettom																		
COMMENTS: Wires hanging from bottom.																		
							2/	11/25										
		EMPLOYEE'S FUL					port is deer	DATE ned to be true	and accurat	e to the be	st of my knowl		PLOYEE'S SI the date liste				_	