RTR Services Inc. HEAVY TRUCK									RTR #: 5013359-02 ACCOUNT NUMBER:									
CONDITION REPORT					0			ACCOUNT NOMBER:										
YEAR: 2016		МІ	LES	523986	;		VIN #:											
	MAKE:	Peterbilt		GV	/W:	Unkno	LICENSE:				ST:		TAGS:	MON	тн	YR:		
MODEL: Columbia 120)	W	WHEELBASE:				COLOR:	EXTERIOR: Red			INTE	RIOR:	Gray				
ENGINE: Detroit		Detroit 12.7L	7L		HP 588 B		ODY TYPE: SI		eeper KEYS:		KEYS:	IGNITION: 🛛 YES 🗌						
TRANS: 13 Speed		13 Speed			FUEL: 🗌 GA		S 🖾 DIESEL		ANTIFREEZE T		ESTED: 🗌 YES 🖾 NO 🛛 🛛 F			RATI	RATING:			
DOES MOTOR RUN? X YES			S) C		LLISION DAMAGE?											
PHYSICAL APPEARANCE																		
	FRONT BUMPER		GD	FR									-					
	HEAD LIGHTS HOOD TURN SIGNALS			\boxtimes											BRAKES			
							Paint Is Peeling											
<u>ک</u>	GRILLE			\boxtimes														
			\boxtimes															
вору	D DOOR			\square			Paint Is Pe	Paint Is Peeling							☑ PWR SEATS☑ PWR MIRRORS			
	REAR BUMPER													AIR CONDITIONER				
	TAILLIGHTS		\boxtimes										ᅴ님	AIR RIDE SEAT D/P				
	P FRONT FENDER		\boxtimes											CONV. 5 TH WHEEL				
	P FRONT DOOR		\square			Paint le Po	Deiné la Deoling							SLIDING 5 TH WHEEL				
	ТОР						Paint Is Pe	Paint Is Peeling Paint Is Peeling								CD / CB	? <u>CD</u>	
S	D FRONT						20 % 275/80/22.5 SIZE:							☑ TAPE / CD / CB? <u>CD</u> ☑ SLEEPER SIZE? <u>S</u> ☑ ELECTRICAL PIGTAIL				
	D REAR A2 (S/D?)						20 % 295/75/22.5 SIZE: 20 % 295/75/22.5 SIZE:							ELECTRICAL PIGTAIL				
TIRES	P FRONT						20 % 275/80/22.5 SIZE:							FUEL TANKS				
	P REAR A1 (S/D?) □ P REAR A2 (S/D?) □						20 % 295/75/22.5 SIZE: 20 % 295/75/22.5 SIZE:							□ SINGLE GAL □ DUAL GAL				
	SPARE					% SIZE:								MUD FLAPS				
s	WINDSHIELD D FRONT DOOR		\mathbb{N}										WF	WHEELS				
GLAS	REAR	WINDOW																
		NT DOOR									_	□ BUD □ SPOKE						
	DASH DOOR PANELS						Missing Pa								IST S/D?	<u>s</u>		
ERIOR				\boxtimes								່ວນ	□ □ □ SUSPENSION □ AIR □ SPRING					
ERI		SEAT(S)		\square													_	
I Z	HEADL	HEADLINER 🗌		\boxtimes	ļĦ)		
<u> </u>	SLEEP	SLEEPER GD		FR	PR		N/A CO		ENTS:					$- \square$				
MECHANICAL	ENGINE			\boxtimes											TOOL		-	
		TRANSMISSION		\boxtimes											LIFT/TA WET K			
				\boxtimes												11		
	BRAKE	BRAKES 🗌		\boxtimes														
ž	FRONT END Image: Constraint of the second secon			\boxtimes										\exists				
	BATTE	RY/ELECTR		\boxtimes						D =-					-			
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																		
COMMENTS: Mileage Unverified. Paint is peeling throughout.																		
							2/4/202			_								
		EMPLOYEE'S FULI				-		ATE		. –			EMPLOYEE'S					
i			All informa	tion cor	ntained	within this r	eport is deemed to b	be true a	and accurate t	o the b	pest of my kr	nowledge a	s of the date li	sted above	9.			

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 0125