	LATBE	Services In D/CAR HAU	JLER	4			Ţ			۸۵۵۵		RTR CCOUN	TI	501355	50-01		
CONDITION REPORT YEAR: 2023				BODY	TYPE:	Dump			ACCOUNT NAME: VIN #: 4L5SC2320PF067126								
MAKE:		Behnke	се			R CAPA	CITY N/A										
MODEL:		Dump Trailer			C	OLOR:	EXTERIOR: Red										
LENGTH:		23'			,	WIDTH:	102			HEIGHT:					GVW : 16,000		
HITCH:		⊠ GOOSE N	ENECK [WHEEL PIN 1] 1 7/8" E	"BALL 🗌		2" BALL					
CAN IT BE TOWED?			S	□ NO	C	COLLISION DAMAGE? PHYSICAL APPEA			☐ YES	S NO KEYS:			EYS:	☐ YE	ES	⊠ NO	
GD I						P	HYSICAL	APPEA	RANCE								
	FRONT PANEL HITCH D SIDE PANEL D SIDE TIE DOWNS			FR N N N	PR	N/A		MENTS							□ SI □ AI □ EI	R RIDE PRING S IR BRAI LECTRI	CAL BRAKES
P SIDE P SIDE REAR TOP RAMP(SIDE D REAR		OOR DOOR													SI WHE] BUD] SPOKI] STEEL] ALUMI OOL BO	XLE E INUM X
TIRES	D REAR A1 (S/D?) D REAR A2 (S/D?) D REAR A3 (S/D?) P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?) P REAR A3 (S/D?) SPARE		6												☐ MUD FLAPS ☐ LOADING RAMP ☐ BATTERY ☐ DOVE TAIL ☐ TILT BED ☐ WEDGE ☐ WINCH ☐ SPARE TIRE RACK		
CLEAF SLIDE LANDI AIR HO		GHTS L LIGHTS ANCE LGT AXLES NG GEAR DSE/GLAD RIC PIGTAIL						COMM	EN15:							EAR DO ANDEM DE DOO FT/TAG NCLOSE	OR AXLE DR AXLE
	THIS IS	NOT A MECHA	NICAL	INSP	ECTIC	N/IT IS	A VISU	AL INSPE	CTION C	NLY / WE	RE	СОММЕ	ND Y	OU INSF	ECT P	RIOR TO	PURCHASE
CO	MMENTS	S:															
							3/5	5/2025									
		EMPLOYEE'S FULI	•					DATE						LOYEE'S SI		=	
			All informa	ation co	ntained v	ithin this rep	oort is deen	ned to be true	and accura	ite to the best	of my	knowledge	as of th	he date liste	d above.		