RTR Services Inc.						4 HHH:	\overline{D}			RTR #: 5013639					9-01			
DUMP TRUCK					,	(((((((((((((((((((}		ACCOUNT NUMBER:								
CONDITION REPORT												CCOUNT NAM						
YEAR: 2011			_	.ES	246,793				VIN #: 1M2AX04C7BM010598		1010598							
MAKE: Mack			GVW:			D HEIGH	_			BED LENGTH			VIDTH					
MODEL: GU713				WHEE		BASE:						XTERIOR:	Black	INTER		Gray		
ENGINE: M		Mack MP8	Mack MP8							EYS: IGNITION: 🛛 YES 🗌 NO 🔹 DOOR			∷ ⊠ YES □ NO					
TRANS: Automatic		T	FUEL: GAS		L			NTIFREEZE TESTED: ☐ YES ☒ NO			RATING:							
DOES MOTOR RUN? YES NO COLLISION DAMAGE? YES NO																		
PHYSICAL APPEARANCE																		
	FRONT	GD	FR	PR 🗵	N/A		D side dented							PTIONS FEERING				
	HEADLIGHTS HOOD TURN SIGNALS						D side defiled								BRAKES			
				\boxtimes											$oxed{oxed}$ AIR			
				\boxtimes										□ HYD				
	GRILLE D FRONT FENDER		片片	\boxtimes	H									$-\mid \boxtimes \mid$	PWR LO	INDOWS		
BODY	D DOOR			\boxtimes											PWR SE			
	D DUMP BED			\boxtimes										$\Box \Box$		IRRORS		
	REAR GATE			\boxtimes										$-\mid \boxtimes \mid$		NDITIONER DE SEAT D/P		
	REAR PANEL					lΗ								ᅱ旹		DE SUSPENSIO	N	
	P FRONT FENDER			\boxtimes										\boxtimes	AM FM			
	P FRONT DOOR P DUMP BED													$\dashv \Box$	CD / CB HITCH 1			
	TOP			\boxtimes										\dashv \Box	TARPS			
S	D FRONT						% 50	SIZE: 1	1R	24.5					TANDE	M AXLE		
	D REAR A1 (S/D?)			\boxtimes			% 50	SIZE: 1	1R	22.5					ENGINE	BRAKE		
	D REAR A2 (S/D?)			\boxtimes			% 50	SIZE: 1	1R	22.5					TOOL B	30X		
TIRES	P FRONT			\boxtimes			% 50	SIZE: 1	1R	24.5				FUI	EL TANK			
T	P REAR A1 (S/D?)			\boxtimes			% 50	SIZE: 1	1R	22.5						SLE GAL	_	
	P REAR A2 (S/D?)			\boxtimes				SIZE: 1		22.5					_	L GAL		
	SPARE WINDSHIELD				H		%	SIZE	<u>:</u>					┙╬	MUD FL EELS	.APS		
SS	D FRONT DOOR													- '''		MINUM		
GLAS	REAR WINDOW					\boxtimes									☐ STEI			
返 P FRO MIRRO		NT DOOR																
DASH		N.S	H		H	H								\exists_{\Box}	☐ SPO	ST S/D?		
ਲ	DOOR PANELS				\boxtimes		D sid	le missii	ng					SU	SPENSIO	N	_	
INTERIOR	SEAT(S)				\boxtimes		D sid	le crack	ed/	P side sta	ain	ed			☐ AIR			
	FLOORING				\boxtimes		Dirty	r										
=	HEADLINER DUMP BED			\boxtimes										\dashv \vdash	☐ PAD			
	DUNIP	BED	GD	FR	PR	UKN	N/A	COMN	ΛΕΝ	NTS:				$\exists \exists$	ARTICU	AG AXLE ILATED		
MECHANICAL	ENGINE			\boxtimes											BED CA	PACITY		
	TRANSMISSION							Whee	1 S	eals leak	ing	g						
	CLUTCH DIFFERENTIALS						$\boxtimes \Box$											
	BRAKES													ᅱ旹				
ME	FRONT END			\boxtimes														
	REAR END BATTERY/ELECTR			\boxtimes										$\exists \exists$				
	THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE																	
то	TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																	
COMMENTS: Mileage Unverified.																		
							.	11/07										
							2/	11/25										

DATE

EMPLOYEE'S FULL NAME (PLEASE PRINT)

EMPLOYEE'S SIGNATURE

All information contained	within this report is deer	med to be true and accu	rate to the best of my kr	nowledge as of the date	e listed above.	
	All information contained	All information contained within this report is deer	_All information contained within this report is deemed to be true and accu	All information contained within this report is deemed to be true and accurate to the best of my for the following	All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date.	All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.