RTR Services Inc.											RTR #: 5023535									
BOX TRUCK					ars are		: : ::			ACCOUNT NUMBER:										
CONDITION REPORT					_			0 1		ACCOUNT NAME:										
YEAR: 2014				_ES	115,569				VIN #: 1HTMMAAN2EH77			9290								
MAKE: International		.1	GV		•	33,000 BO			2'4"		LENG			BOX \	WIDTH					
MODEL: 4300 SBA				WH	IEELE	BASE:					EXTER		White		INTER		White/ Silver	r		
ENGINE: MaxxForce			DT	HP						GNITION: ☐ YES ⊠ NO • DOOR				: ☐ YES ⊠ NO						
TRANS: Manual						☑ DIE	DIESEL ANTIFREEZE TESTED: ☐ YES ☒ NO					RATII	NG:							
ı	DOES M	OTOR RUN?	D	YES	⊠I	NO	COLL	ISION DA				⊠ NO								
									CAL APPE	EARAI	NCE									
ВОДУ	FRONT	BUMPER	GD	<u>FR</u> ⊠	PR	N/A	CC	<u>OMMENTS</u>									OPTIONS TEERING			
	HEADL	_													_	BRAKES				
	HOOD TURN SIGNALS GRILLE			$\boxtimes$												⊠ AIR □ HYD				
			$  \; \square \;  $												$\dashv_{\boxtimes}$	PWR L				
	D FRONT FENDER			$\boxtimes$													/INDOWS			
	D DOO D BOX			$\boxtimes$												PWR SI	EATS IIRRORS			
		BUMPER		$\boxtimes$	Ħ												NDITIONER			
	TAILLIO REAR I	-		$\boxtimes$													DE SEAT D/P DE SUSPENSION	_		
	P FRONT FENDER P FRONT DOOR P BOX			$\boxtimes$	H										$\dashv               $	AM FM				
															$\neg \neg$	CD / CE				
	TOP			$\boxtimes$											$\exists \exists$		ER SIZE?			
TIRES	D FRONT			$\boxtimes$			%	50 <b>SIZE</b> :								E-TRAC	CK LINING			
	D REAR A1 (S/D?)			$\boxtimes$				50/50 SIZ									OME LIGHT			
	D REAR A2 (S/D?) P FRONT						%	SIZ 50 SIZE:	<u>'E:</u>					┦╏	SIDE D EL TANK					
	P REAR A1 (S/D?)							50/50 SIZE:	<b>7</b> E ·					╡ . 。		GLE GAL				
	P REAR A2 (S/D?)						%	SIZ							-		AL GAL			
	SPARE WINDSHIELD				$\Box$		%	SIZ	'E:								LAPS			
တ္	D FRONT DOOR											WHEELS  ☐ ALUMINUM								
GLAS		REAR WINDOW											⊠ STEEL							
ับ	P FRONT DOOR MIRRORS		$    \square   $				М	Missing A Bubble Mirror On Driver Front Bum				ner	_							
<u>~</u>	DASH			$\boxtimes$			171	Wissing A Buoole Willor On Driver Front Bumper				ірсі	$\dashv$	_	JST S/D?					
	DOOR PANELS SEAT(S) FLOORING HEADLINER SLEEPER BOX			$\boxtimes$									SU	SPENSIO						
RIC				$\boxtimes$												☐ AIR ⊠ SPR				
INTERIOR				$\boxtimes$	□										☐ PAD	)				
_														$\dashv$ $\Box$		M AXLE E BRAKE				
			GD	FR	PR	UKN	N/A	N/A COMMENTS:								вох				
	ENGINE TRANSMISSION CLUTCH DIFFERENTIALS BRAKES FRONT END REAR END BATTERY/ELECTR REFRIGERATION								Compress	sion							AG AXLE			
MECHANICAL						$\boxtimes$										RAMP LIFTGA	\TF			
																	RA SYSTEM			
															$\exists  \exists$					
					$\mid \exists \mid$										╛╘					
								TD1	T7.	<b>T</b>					$\exists  \exists$					
THI			CAL INS	PFC	ION /	IT IS A	∐ VISU	Ther	mo King	ğ 1-80 <b>NI Y</b> /1	DFF & I	OPF FI	INCTIONS	NOT	FRIFIE	D BUYE	R RESPONSIBI F	F		
THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / DEF & DPF FUNCTIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE																				
COMMENTS: Mileage Unverified.																				
_ 3/13/2025																				
		EMPLOYEE'S FUL						DA deemed to be	TE	curate to	the best o	f my kno		OYEE'S he date lis						