

RTR Services Inc. TRAILER CONDITION REPORT RTR #: 5023909-01 ACCOUNT NUMBER: ACCOUNT NAME:



YEAR: 2017 BODY TYPE: Dry Van VIN #: 1GRAP0628JJ110496

MAKE: Great Dane

MODEL: CCC-3314-01053 COLOR: EXTERIOR: White INTERIOR: White

LENGTH: 53ft WIDTH: 8-6' HEIGHT: 13'-6" GVW: 68,000 LB

HITCH: [] GOOSE NECK [] PINTLE [x] 5TH WHEEL PIN [] 1 7/8" BALL [] 2" BALL [] 2 5/16" BALL

CAN IT BE TOWED? [x] YES [] NO COLLISION DAMAGE? [] YES [x] NO KEYS: [] YES [x] NO

PHYSICAL APPEARANCE

Table with columns for BODY, INTERIOR, TIRES, MECHANICAL, and COMMENTS. Rows include items like FRONT PANEL, HITCH, D SIDE PANEL, etc., with checkboxes for condition (GD, FR, PR, N/A, UKN) and a list of options on the right.

THIS IS NOT A MECHANICAL INSPECTION / IT IS A VISUAL INSPECTION ONLY / FOR REEFER UNITS: EMISSIONS NOT VERIFIED, BUYER RESPONSIBLE TO VALIDATE / WE RECOMMEND YOU INSPECT PRIOR TO PURCHASE

COMMENTS:

3/28/25

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE

All information contained within this report is deemed to be true and accurate to the best of my knowledge as of the date listed above.